

<b>PCN Number:</b>	20151216001	<b>PCN Date:</b>	12/17/2015
<b>Title:</b>	Datasheet for DRV2604		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Change Type:</b>			
<input type="checkbox"/> Assembly Site	<input type="checkbox"/> Design	<input type="checkbox"/> Wafer Bump Site	
<input type="checkbox"/> Assembly Process	<input checked="" type="checkbox"/> Data Sheet	<input type="checkbox"/> Wafer Bump Material	
<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Part number change	<input type="checkbox"/> Wafer Bump Process	
<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Site	<input type="checkbox"/> Wafer Fab Site	
<input type="checkbox"/> Packing/Shipping/Labeling	<input type="checkbox"/> Test Process	<input type="checkbox"/> Wafer Fab Materials	
		<input type="checkbox"/> Wafer Fab Process	

### Notification Details

#### Description of Change:

Texas Instruments Incorporated is announcing an information only notification etc.

The product datasheet(s) is being updated as summarized below.

The following change history provides further details.



**DRV2604**

SLOS824B –DECEMBER 2012–REVISED DECEMBER 2015

#### Changes from Revision A (July 2015) to Revision B

Page

- |   |    |
|---|----|
| • Changed $t_{h(1)}$ Hold time, SCL to SDA from 10 ns to 50 ns in <a href="#">Timing Requirements</a> ..... | 5  |
| • Changed the default value of NG_THRESH[1:0] from 1 to 2 in the <i>Register Map</i> .....                  | 45 |

Device Family	Change From:	Change To:
DRV2604	SLOS824A	<b>SLOS824B</b>

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/DRV2604>

#### Reason for Change:

To more accurately reflect device characteristics.

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

#### Changes to product identification resulting from this PCN:

None.

#### Product Affected:

DRV2604YZFR	DRV2604YZFT
-------------	-------------

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>

