MICROCHIP

Product Change Notification / MDTM-7DSMKU

Date:

05-Oct-2002

Notification Subject:

MPLAB v5.70.40 Dot Release

Notification Text:

MPLAB v5.70.40 is released to the Microchip web site, available at
http://www.microchip.com/1010/pline/tools/picmicro/devenv/mplabi/mplab5x/index.htm

Listed below is the device support for MPLAB v5.70.40. Some of these devices were also supported in the last interim release, MPLAB v5.70.20.

Note that the PICSTART Plus will need to be upgraded to support the new parts. A new hex file is included with MPLAB v5.70.40. A blank 17C44 can be programmed with this code to replace the current PICSTART Plus controller. Information is available in the on-line help of MPLAB that details the upgrade procedure for PICSTART Plus. An upgrade kit will also be made available when this firmware is released to production (planned in November, part number UK003006).

MPLAB ICE 2000
PCM12XB0: PIC12F629/675
PCM16XQ1: PIC16F745/765
PCM16XV0: PIC16F877A/876A/874A/873A

MPLAB SIM/MPASM/MPLINK
PIC18F4320/2320/4220/2220
PIC18F1320/1220
PIC16F630
PIC16F676
PIC16F818/819
PIC16F627A/628A
PIC16F87/88
PIC16C557

PRO MATE II
PIC18F1320/1220
PIC18F4320/2320/4220/2220

PIC16F676
PIC16F630
PIC16F818/819
PIC16C557
Improvements and enhancements for HCS362/365

PICSTART Plus
PIC16F877A/876A/874A/873A
PIC12F629/675
PIC16F818/819
PIC16F676
PIC16F630