



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

**PCN#20230213000.0
Symbolization update for select TSSOP devices
Information Only**

Date: February 14, 2023
To: Digi-Key PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Team (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services

20230213000.0
Attachment: 1

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
DRV8833CPWP	null
DRV11873PWPR	null
TPS40060PWPR	null
TPS40071PWPR	null
DRV10974PWPR	null
TPS54494PWP	null
TPS54357PWP	null
TPS40057PWP	null
TPS61031PWPR	null
TPS54395PWP	null
TLV2475IPWPR	null
TPS54394PWPR	null
TPS40071PWP	null
SN65LVDS32PW	null
TPS1HB50BQPWPRQ1	null
DRV8860PW	null
LM43601AQPWPTQ1	null
SN65LVDT348PWR	null
DAC8581IPW	null
LM53602AMPWPR	null
TPS2HB35AQPWPRQ1	null
BQ76200PWR	null
TPS1HB35FQPWPRQ1	null
LM43600QPWPTQ1	null
LM43600PWPT	null
SN65LVDS047PW	null
TPS62110HPWP	null
LM46000PWPR	null
SN65LVDS050PW	null
TPS40021MPWPEP	null
TPS7A6333QPWPRQ1	null
BQ77PL157APW-4225	null
TPS1HB35AQPWPRQ1	null
TPIC6C596PW	null
TPS1HB35BQPWPRQ1	null
DAC5578SPWR	null
SN65LVDS33PW	null
DAC8581IPWR	null
TLV1544CPWR	null
TAS5411QPWPRQ1	null
LM76202QPWPRQ1	null
TLV2544IPW	null
LM536025QPWPTQ1	null
DRV8803PWP	null
TPS54292PWPR	null
DRV8876PWPR	null
DAC8164IAPW	null
TPS61120PW	null
LM53603AQPWPTQ1	null
MSP430FR2111IPW16R	null
TPS2HB16BQPWPRQ1	null
TSC2046IPW	null
TPS2HB16FQPWPRQ1	null
DAC6573IPWR	null
LM43600PWP	null
DAC8580IPW	null
SN65LVCP22PW	null

SN65MLVD047PW	null
TPS26600PWPR	null
TPS1H100AQPWPRQ1	null
TPS65320QPWPRQ1	null
MSP430FR2100IPW16R	null
LM26001QMXA/NOPB	null
TLV5604CPW	null
LM5156HPWPR	null
SN65LVDS050PWPR	null
DAC8564ICPW	null
LM74202QPWPRQ1	null
DAC6573IPW	null
LM43603PWPT	null
MSP430FR2512IPW16	null
DRV8860APWR	null
MSP430FR2311IPW16R	null
DRV8801PWP	null
ADS7280IPWR	null
SN65LVDS122PW	null
TLV5604IPWR	null
LM46002AQPWPTQ1	null
BQ76200PW	null
LM46001QPWPTQ1	null
TPS92691QPWPRQ1	null
LM43603QPWPRQ1	null
LM53603AQPWPRQ1	null
TPS1HA08CQPWPRQ1	null
LM51561HQPWPRQ1	null
LM26001BMH/NOPB	null
MSP430FR2522IPW16	null
SN65LVDS31PWR	null
TLC6C598PWR	null
TPS1HB16AQPWPRQ1	null
DRV8800PWP	null
SN65LVDS051PW	null
DRV8860PWPR	null
TPS40055PWPRG4	null
TPS40055PWPR	null
TPS54290PWP	null
TPS54494PWPR	null
TPS54291PWP	null
TPS55383PWP	null
TPS40061PWPR	null
TPS542941PWPR	null
TPS40056PWP	null
DAC8565IAPW	null
LM43603AQPWPRQ1	null
TPS2HB50AQPWPRQ1	null
MSP430FR2110IPW16	null
LM46002PWPT	null
ADS8329IPW	null
LM46002QPWPTQ1	null
DRV8816PWPR	null
DAC7678SPW	null
LM43601PWPR	null
ADS8330IPW	null
ADS7229IPW	null
SN65LVDM051PW	null
LM536023QPWPTQ1	null
ADS8327IPW	null
TPS1HB08FQPWPRQ1	null
SN65LVDT122PW	null
DAC7564ICPW	null
ADS8327IBPW	null
LM46001AQPWPTQ1	null
LM46001PWPT	null
SN65LVDM22PW	null
DAC7565ICPW	null
LM46000QPWPTQ1	null
SN65LVDS33PWR	null

MSP430FR2311IPW16	null
TPS2HB50BQPWPRQ1	null
TPS92691QPWPQ1	null
SN65LVDT348PW	null
TPS26400PWPR	null
SN65LVDS049PW	null
LDC2112PWT	null
DRV8874PWPR	null
TPS54356PWP	null
TPS54354PWP	null
TPS40054PWPG4	null
TPS23751PWPR	null
TPS54292PWP	null
DRV8876NPWPT	null
TPS40061PWP	null
LM43602PWP	null
TPS54386TPWPRQ1	null
SN65LVDM050PW	null
LM46002PWP	null
ADS8330IBPW	null
TLV5614MPWREP	null
DAC8564IAPW	null
DAC7565IAPW	null
ADS8328IBPW	null
TPIC6C595PWG4	null
TLV0834IPW	null
LM43602QPWPTQ1	null
PGA281AIPW	null
SN65LVDT348PWG4	null
MSP430FR2310IPW16	null
TPS1HB08BQPWPRQ1	null
LM46002AQPWPRQ1	null
PGA302EPWT	null
TPS65320BQPWPRQ1	null
TPS1HB16BQPWPRQ1	null
SN65LVDS048APWG4	null
TSC2046EIPWR	null
LM26001MXA/NOPB	null
LM51561HPWPR	null
DRV8860APW	null
DAC7578SPWR	null
TLV1544CPW	null
DAC8554IPW	null
ADS7280IPW	null
TLV5614IPW	null
TPS1HA08BQPWPRQ1	null
LM43602AQPWPTQ1	null
SN65LVDS047PWR	null
SN65LVDS391PW	null
SN65LVDT390PWR	null
PGA460TPWRQ1	null
LM43603PWP	null
DAC8554IPWR	null
LM53603AMPWPR	null
TPS40055PWP	null
TPS23751PWP	null
DRV8803PWPR	null
TPS61032PWP	null
TPS54495PWPR	null
TPS40051PWP	null
TPS61030PWR	null
TPS54295PWPR	null
TPS40060PWP	null
TPS55386PWP	null
DAC6578SPW	null
TPS1HA08AQPWPRQ1	null
ALM2402QPWPRQ1	null
DAC7578SPW	null
TPS54550PWPR	null
TLV5627IPW	null

LM43603AQPWPTQ1	null
SN65MLVD047APW	null
LM43601QPWPRQ1	null
TPS1HB50AQPWPRQ1	null
LM46000AQPWPRQ1	null
SN65LVDS391PWR	null
LM53602AQPWPRQ1	null
TPS1HA08EQWPRQ1	null
PGA281AIPWR	null
LM43600QPWPRQ1	null
LM46000AQPWPTQ1	null
UCD7100APWP	null
ADS8328IPW	null
TPS40055MPWPREP	null
LM26001QMXAX/NOPB	null
DAC8534IPWG4	null
TAS5421QPWPRQ1	null
DRV8860PWR	null
MSP430FR2100IPW16	null
TSC2013QPWRQ1	null
TPS27SA08CQPWPRQ1	null
LM43601PWP	null
TPS27SA08CPWPR	null
LM43600AQPWPTQ1	null
TPS7B7701QPWPRQ1	null
TSC2046EIPW	null
SN65LVDS349PW	null
TSC2046IPWR	null
LM5156HQPWPRQ1	null
TPS92691QPWPTQ1	null
ADS7279IPW	null
TPS40060PWPRG4	null
TPS40020PWP	null
TPS55386PWPR	null
TPS54352PWP	null
DRV8833CPWPR	null
DRV8874QPWPRQ1	null
TPS61032PWPR	null
TPS542941PWP	null
DRV8876NPWPR	null
PGA460TPWQ1	null
SN65LVDS390PW	null
MSP430FR2000IPW16	null
SN65LVDT33PW	null
LM46000PWPT	null
TPS2HB35CQPWPRQ1	null
DAC8580IPWR	null
SN65LVDS048APW	null
TPS1HB35CQPWPRQ1	null
TPIC6C595PW	null
LM536035QPWPRQ1	null
DRV8800PWPR	null
TLV1504IPWR	null
LM43602QPWPRQ1	null
DAC5573IPW	null
TPS1HA08DQPWPRQ1	null
LM43600PWPR	null
TLV5614CPW	null
LM536033QPWPTQ1	null
LDC2114PWT	null
DRV8816PWP	null
DAC8534IPW	null
TPS61175QPWPRQ1	null
TPS1HB16FQPWPRQ1	null
LM43601PWPT	null
DAC8574IPWG4	null
SN65LVDM051PWR	null
LM53602AMPWPT	null
PGA460TPWR	null
TPS40050QPWPRQ1	null

TPS2HB35BQPWPRQ1	null
TPS1HB08AQPWPRQ1	null
LM46000QPWPRQ1	null
LM53602AQPWPTQ1	null
LM34966QPWPRQ1	null
DRV8801PWPR	null
ADS1230IPW	null
TPS542951PWP	null
TPS54356PWPR	null
TPS54394PWP	null
DRV8876PWPT	null
TPS40057PWPR	null
TPS54350PWPR	null
TPS54291PWPR	null
DRV8805PWP	null
TPS40077PWP	null
DRV8805PWPR	null
TPS61030PWP	null
TPS40054PWP	null
TPS40054PWPR	null
TPS54350PWP	null
TPS542951PWPR	null
BUF06703PWR	null
LM43602PWPT	null
PGA460TPW	null
TPS61131PW	null
LM43603PWPR	null
LM46000PWP	null
LM46001PWPR	null
SN65LVDS048APWR	null
DAC7573IPW	null
TPS1H100BQPWPRQ1	null
LM46001QPWPRQ1	null
MSP430FR2110IPW16R	null
MSP430FR2422IPW16R	null
TPS7A6350QPWPRQ1	null
TPS2HB16AQPWPRQ1	null
TPS54550PWPG4	null
MSP430FR2422IPW16	null
DAC8574IPW	null
LM53603AMPWPT	null
SN65LVDS049PWR	null
TPS54550PWP	null
TPS61130PW	null
SN65LVDT390PW	null
SN65LVDS348PWR	null
TPS26600PWPT	null
LM46002PWPR	null
TLC6C598QPWRQ1	null
SN65LVDS31PW	null
TPS40077PWPR	null
TLV2475AIPWPR	null
TPS55383PWPR	null
DRV8804PWP	null
TPS40021PWP	null
TPS54294PWP	null
TPS40055PWPG4	null
BQ77PL157APWR-4225	null
LM43602PWPR	null
TPS61120PWR	null
SN65LVDS22PW	null
SN65LVDT33PWR	null
TPS92630QPWPRQ1	null
DAC8565ICPW	null
LM43603QPWPTQ1	null
TPS2013APWP	null
DAC5578SPW	null
LM26001MXAX/NOPB	null
DAC7564IAPW	null
TPS54225TPWPRQ1	null

TPIC6C596PWRG4	null
SN65LVDS32PWR	null
SN65LVDS390PWR	null
LM46001PWP	null
SN75LVDS391PW	null
TLV5604IPW	null
LM536035QPWPTQ1	null
TPIC6C595PWR	null
TPS26602PWPR	null
DAC8555IPW	null
ADS8329IBPW	null
MSP430FR2111IPW16	null
SN65LVDS348PW	null
LM46002QPWPRQ1	null
ADS1230IPWR	null
TPS26602PWPT	null
TPIC6C596PWR	null


Technical details of this Product Change follow on the next page(s).

PCN Number:	20230213000.0	PCN Date:	February 14, 2023
Title:	Symbolization update for select TSSOP devices		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Assembly Process
<input type="checkbox"/>	Design	<input type="checkbox"/>	Assembly Materials
<input type="checkbox"/>	Test Site	<input checked="" type="checkbox"/>	Datasheet
<input type="checkbox"/>	Wafer Bump Site	<input type="checkbox"/>	Packing/Shipping/Labeling
<input type="checkbox"/>	Wafer Fab Site	<input type="checkbox"/>	Mechanical Specification
		<input type="checkbox"/>	Test Process
		<input type="checkbox"/>	Wafer Bump Material
		<input type="checkbox"/>	Wafer Bump Process
		<input type="checkbox"/>	Wafer Fab Materials
		<input type="checkbox"/>	Wafer Fab Process
		<input type="checkbox"/>	Part number change

PCN Details

Description of Change:

This letter is to inform customers of a device symbolization change for select devices in the TSSOP package that will enable enhanced device level traceability as follows:



Reason for Change:

Improved Device traceability

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

None

Changes to product identification resulting from this PCN:

Added device symbolization row

Product Affected:

See page 2

For questions regarding this notice, e-mails can be sent to the contacts shown below or your local Field Sales Representative.

Location	E-Mail
WW Change Management Team	PCN_ww_admin_team@list.ti.com

IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, or other requirements. These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to TI's Terms of Sale (www.ti.com/legal/termsofsale.html) or other applicable terms available either on ti.com or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.