

Title of Change:	AR0130CS Datasheet Update
Effective date:	9 January 2019
Contact information:	Contact your local ON Semiconductor Sales Office or <Sonya.Yip@onsemi.com>
Type of notification:	This Product Bulletin is for notification purposes only. ON Semiconductor will proceed with implementation of this change upon publication of this Product Bulletin.
Change Category:	<input type="checkbox"/> Wafer Fab <input type="checkbox"/> Assembly Change <input type="checkbox"/> Test Change <input checked="" type="checkbox"/> Other <u>Documentation</u>


Change Sub-Category(s):	<input type="checkbox"/> Manufacturing Site Addition <input type="checkbox"/> Material Change <input checked="" type="checkbox"/> Datasheet/Product Doc change <input type="checkbox"/> Manufacturing Site Transfer <input type="checkbox"/> Product specific change <input type="checkbox"/> Shipping/Packaging/Marking <input type="checkbox"/> Manufacturing Process Change <input type="checkbox"/> Other: _____
--------------------------------	--

Sites Affected:	ON Semiconductor Sites: None	External Foundry/Subcon Sites: None
------------------------	---------------------------------	--

Description and Purpose:
 AR0130CS Datasheet was updated to correct an error. These changes do not affect form, fit, or function of the product.

AR0130CS Datasheet Changes

1. Updated Figure 3, "48-Pin iLCC Pinout Diagram"



List of Affected Parts:	AR0130CSC00SPBA0-DP1	AR0130CSC00SPCA0-DPBR1	AR0130CSC00SPCA0-DRBR1
	AR0130CSC00SPBA0-DR1	AR0130CSC00SPCA0-DRBR1	



Appendix A: Changed Products

Product	Customer Part Number
AR0130CSSC00SPBA0-DP1	
AR0130CSSC00SPBA0-DR1	
AR0130CSSC00SPCA0-DPBR1	
AR0130CSSC00SPCA0-DRBR1	
AR0130CSSM00SPCA0-DRBR1	