



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001031I

DATE: 25-Jan-2021

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	806-0468-85	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	806-0473-20+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	806-0506-30+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	806-0506-30+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DG201ADJ+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DG445ETE+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DG445ETE+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DS1088LU-50+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DS1088LU-50+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DS1091LUA-172/V+	MAX31091AUA/V+172	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DS1091LUA-172/V+T	MAX31091AUA/V+T172	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DS1705EUA+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DS1801E-02V+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DS1801E-02V+T&R	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DS1810R-10-U+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DS18S20-PAR+T&R	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DS2501P+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DS2501P+T&R	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	DS2504AN-600-00+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	ICL7660ESA+TG002	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX1063BCEG+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX1063BCEG+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX11640EEG+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX1188AEUP+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX1425EAI+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX14739EWT+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-Feb-2021

Discontinuance	MAX14739EWT+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX1497EAI+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX158ACWI+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX16039PLA31+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX16039PLA31+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX16088US33A+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX16088US33A+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX16090UK10AAB+	N/A	25-Jan-2021	25-Jan-2021	The part was not released
Discontinuance	MAX16090UK10AAB+T	N/A	25-Jan-2021	25-Jan-2021	The part was not released
Discontinuance	MAX16090UK46WJB+	N/A	25-Jan-2021	25-Jan-2021	The part was not released
Discontinuance	MAX16090UK46WJB+T	N/A	25-Jan-2021	25-Jan-2021	The part was not released
Discontinuance	MAX16091UK23OMB+	N/A	25-Jan-2021	25-Jan-2021	The part was not released
Discontinuance	MAX16091UK23OMB+T	N/A	25-Jan-2021	25-Jan-2021	The part was not released
Discontinuance	MAX16092UK26OOA+	N/A	25-Jan-2021	25-Jan-2021	The part was not released
Discontinuance	MAX16092UK26OOA+T	N/A	25-Jan-2021	25-Jan-2021	The part was not released
Discontinuance	MAX16942EGEE/V+CLT	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX16942EGEE/V+CMY	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX17007AEVKIT+	N/A	25-Jan-2021	26-Jul-2022	EVKIT is No Longer Supported
Discontinuance	MAX17042G+TG075	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX17139ETL+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX17139ETL+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX181CCPL+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX1930ESA+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX1930ESA+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX19792ETX+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX19792ETX+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX20024DGXXI/V+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX20024DGXXI/V+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX20024DGXXJ/V+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX20024DGXXJ/V+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX268BCWG+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX268BCWG+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX3205EATE+TG069	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX3207EAUT+TG11	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX3281EAUT+TG069	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX3374EEKA	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-Feb-2021

Discontinuance	MAX3374EEKA-T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX3378EEBC+TG071	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX3456EETE+TG071	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX398EEE+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX398EEE+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX4125EUA+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX4125EUA+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX4566ESE+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX4566ESE+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX4708EPE+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX505AENG+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX5062AASA+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX5062AASA+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX5353AEPA+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX5364EUT+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX5364EUT+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX538AEPA+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6314US28D3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6314US28D3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6314US28D4+TG71	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6314US31D1+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6314US31D1+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6314US43D2+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6314US43D2+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6315US28D2+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6315US28D2+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6315US46D4+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6315US46D4+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6315US48D2+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6315US48D2+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6358MTUT+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6358MTUT+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6381XR27D3+TG71	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6381XR28D2+CF2	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6390XS16D4+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6390XS16D4+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-Feb-2021

Discontinuance	MAX6394US300D2+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6394US300D2+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6394US310D2+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6394US310D2+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6394US310D4+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6394US310D4+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6394US317D1+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6394US317D1+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6394US455D1+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6394US455D1+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6394US455D3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6394US455D3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6408BS28+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6408BS28+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6412UK42+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6412UK42+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6427EHUR+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6427EHUR+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6593TG9A+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6593TG9A+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6699EE38+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6699EE38+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6711ZEXS+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6711ZEXS+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6717UKTGD6+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6717UKTGD6+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6718UKZWD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6718UKZWD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6719AUTSHD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6719AUTSHD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6719AUTTWD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6719AUTTWD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6719AUTVHD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6719AUTVHD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6719UTLTD1+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6719UTLTD1+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-Feb-2021

Discontinuance	MAX6721AUTWGD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTLTD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTLTD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTRVD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTRVD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTSDD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTSDD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTSHD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTSHD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTSYD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTSYD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTTGD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTTGD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTVDD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTVDD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTWGD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTWGD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTZWD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6721UTZWD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722AUTSVD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722AUTSVD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722AUTSYD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722AUTSYD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722AUTVHD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722AUTVHD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722AUTYDD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722AUTYDD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTLTD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTLTD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTRVD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTRVD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTSHD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTSHD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTTZD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTTZD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTVDD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-Feb-2021

Discontinuance	MAX6722UTVDD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTVHD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTVHD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTWGD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6722UTWGD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6723AUTSVD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6723AUTSVD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6725AKALTD4+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6725AKALTD4+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6725KASHD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6725KASHD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6728KASHD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6728KASHD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6728KASVD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6728KASVD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6731UTTD3+TG48	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6832FXRD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6832FXRD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6834HXRD3+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6834HXRD3+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6837HXSD2+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6837HXSD2+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6866UK23D3L+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6866UK23D3L+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6880ETG+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6880ETG+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6888RETE+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX6888RETE+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX730ACPA+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX7404CPA+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX7414EPA+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX7427EPA+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX77868EFN+	N/A	25-Jan-2021	25-Jan-2021	The part was not released
Discontinuance	MAX77868EFN+T	N/A	25-Jan-2021	25-Jan-2021	The part was not released
Discontinuance	MAX806TESA+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX806TESA+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-Feb-2021

Discontinuance	MAX810MEXR+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX810MEXR+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX822RUS+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX822RUS+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX8510EXK45+G65	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX8510EXK45+TG65	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX8841ELT25+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX8841ELT25+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX8877EUK26+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX8877EUK26+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX8891EXK25+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX8891EXK25+T	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX9027EBT+TG05	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX9027EBT+TG47	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX9027EBT+TWG47	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX9719DETE+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MX7528JEPP+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	MX7533KP+	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT1115MFP	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT1115MFP-004	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT1115SFC	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT1145MFP	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT1188SCFQ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT1189SAFQ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT1193SAFQ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT1195MFP	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT1198SBFQ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT1198SBFQX	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT1198SCFQ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT234WFQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT239WFC-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT240WFC-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT241WFC-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT242WFC-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT242WFC-ADJ-006	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT246BWFQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-Feb-2021

Discontinuance	VT246WFQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT247BWFQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT247WFQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT251AFQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT251FQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT251FQX-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT252AFQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT252AFQ-ADJ-008	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT252FQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT254FQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT261ABWFQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT261BWFQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT262AWFQ-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT356FC-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT358FC-ADJ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured
Discontinuance	VT501FQ	N/A	25-Jan-2021	26-Jul-2022	Part can no longer be manufactured