



Product Change Notification - SYST-17UOQS265

Date:

20 Aug 2018

Product Category:

Voltage References

Affected CPNs:



Notification subject:

Data Sheet - LM4040/4041 - Precision Micropower Shunt Voltage Reference

Notification text:

SYST-17UOQS265

Microchip has released a new DeviceDoc for the LM4040/4041 - Precision Micropower Shunt Voltage Reference of devices. If you are using one of these devices please read the document located at [LM4040/4041 - Precision Micropower Shunt Voltage Reference](#).

Notification Status: Final

Description of Change:

- 1) Corrected part number for Reverse Current in Operating Ratings & Dagger; to LM4041-ADJ.
- 2) Updated Section 6.1 “Package Marking Information” drawing and information.
- 3) Updated information in Product Identification System.
- 4) Updated “Reverse-Breakdown Voltage Change with Operating Current Change” conditions for LM4041-1.2 Electrical Characteristics and LM4041-ADJ Electrical Characteristics

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 20 Aug 2018

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[LM4040/4041 - Precision Micropower Shunt Voltage Reference](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.



To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

LM4040-2.5CYW

LM4040-4.1CYW

LM4040CYM3-2.5-TR

LM4040CYM3-4.1-TR

LM4040CYM3-5.0-TR

LM4040DYM3-2.5-TR

LM4040DYM3-4.1-TR

LM4040DYM3-5.0-TR

LM4040-2.5CYW-8

LM4040-4.1CYW-8

LM4041CYM3-1.2-TR

LM4041CYM3-ADJ-TR

LM4041DYM3-1.2-TR

LM4041DYM3-ADJ-TR

LM4041DYM3-A-TR