


Standardized Information Note (IN)

1. Information Note basic data						
Customer		Name Customer:				
		Contact Email adress:				
1.1 Co		Site:	Melexis leper			
		Affected site(s):	Melexis Supplier	Melexis leper	Melexis Erfurt	Melexis Sofia
1.2 Information Note No.		MCM-5914				
1.3 Title of IN		Business Continuity Plan Unisem Batam Products				
1.4 Issue date		2019/08/05				

2. Contact		
2.1 Contact supplier		
2.1.1 Name		
2.1.2 Phone		
2.1.3 Email		
2.2 Team supplier (optional)		
2.2.1 Name (optional)	2.2.2 Phone (optional)	2.2.3 Email (optional)

3. Description		
	Old	New
Description #1	Assembly house location : Unisem Batam (Indonesia)	Assembly house location : See section 11.
Description #2		

Description #3		
Description #4		
Description #5		

4. Reason / motivation	
4.1 Motivation	Discontinuation communication from Unisem about operations closure at Unisem Batam by 30-Sep-2019.
4.2 Additional explanation (optional)	See the attached information letter for detailed information.

5. Marking of parts / traceability	
5.1 Description	Traceability through lot number and shipment date.

6. Timing / schedule		
6.1 Intended start of delivery		

7. Attachments (e.g. additional documentation, pictures, part list....)	
Information letter - Business Continuity Plan Unisem products.pdf	

8. Affected parts	
8.1 Current	8.2 New (if applicable)

8.1.1 Cust Part No.	8.1.2 Supplier Part Name	8.1.3 Assembly House	8.1.4 Package Name	8.1.5 Part Desc	8.1.6 Addtl Part Info	8.2.2 Supplier Part Name	8.2.3 Assembly House	8.2.4 Package Name
N/A	MLX92211LUA-BAA-015-BU	Unisem Batam	UA GR			MLX92211LUA-BAA-015-BU	Lingsen,	UA GR
N/A	MLX92231LUA-AAA-020-BU	Unisem Batam	UA GR			MLX92231LUA-AAA-020-BU	Lingsen,	UA GR
N/A	MLX92231LUA-AAA-034-BU	Unisem Batam	UA GR			MLX92231LUA-AAA-034-BU	Lingsen,	UA GR
N/A	MLX92241LUA-AAA-004-BU	Unisem Batam	UA GR			MLX92241LUA-AAA-004-BU	Lingsen,	UA GR
N/A	MLX92241LUA-AAA-006-BU	Unisem Batam	UA GR			MLX92241LUA-AAA-006-BU	Lingsen,	UA GR
N/A	MLX92241LUA-AAA-028-BU	Unisem Batam	UA GR			MLX92241LUA-AAA-028-BU	Lingsen,	UA GR
N/A	MLX92241LUA-BAA-026-BU	Unisem Batam	UA GR			MLX92241LUA-BAA-026-BU	Lingsen,	UA GR
N/A	MLX92241LUA-BAA-101-BU	Unisem Batam	UA GR CAP			MLX92241LUA-BAA-101-BU	Lingsen,	UA GR CAP
N/A	MLX92241LUA-BAA-107-BU	Unisem Batam	UA GR CAP			MLX92241LUA-BAA-107-BU	Lingsen,	UA GR CAP
N/A	MLX92241LUA-BAA-108-BU	Unisem Batam	UA GR CAP			MLX92241LUA-BAA-108-BU	Lingsen,	UA GR CAP
N/A	MLX92241LUA-BAA-110-BU	Unisem Batam	UA GR CAP			MLX92241LUA-BAA-110-BU	Lingsen,	UA GR CAP
N/A	MLX92241LUA-BAA-111-BU	Unisem Batam	UA GR CAP			MLX92241LUA-BAA-111-BU	Lingsen,	UA GR CAP
N/A	MLX92241LUA-BAA-112-BU	Unisem Batam	UA GR CAP			MLX92241LUA-BAA-112-BU	Lingsen,	UA GR CAP
N/A	MLX92241LUA-BAA-113-BU	Unisem Batam	UA GR CAP			MLX92241LUA-BAA-113-BU	Lingsen,	UA GR CAP
N/A	MLX92241LUA-BAA-114-BU	Unisem Batam	UA GR CAP			MLX92241LUA-BAA-114-BU	Lingsen,	UA GR CAP
N/A	MLX92242LUA-AAA-300-BU	Unisem Batam	UA GR CAP			MLX92242LUA-AAA-300-BU	Lingsen,	UA GR CAP
N/A	MLX92221LUA-AAA-004-BU	Unisem Batam	UA GR			MLX92221LUA-AAA-004-BU	Lingsen,	UA GR
N/A	MLX92221LUA-AAA-005-BU	Unisem Batam	UA GR			MLX92221LUA-AAA-005-BU	Lingsen,	UA GR
N/A	MLX92221LUA-AAA-006-BU	Unisem Batam	UA GR			MLX92221LUA-AAA-006-BU	Lingsen,	UA GR
N/A	MLX92221LUA-AAA-007-BU	Unisem Batam	UA GR			MLX92221LUA-AAA-007-BU	Lingsen,	UA GR
N/A	MLX92221LUA-BAA-102-BU	Unisem Batam	UA GR CAP			MLX92221LUA-BAA-102-BU	Lingsen,	UA GR CAP
N/A	MLX92221LUA-BAA-103-BU	Unisem Batam	UA GR CAP			MLX92221LUA-BAA-103-BU	Lingsen,	UA GR CAP
N/A	MLX92215LUA-AAA-000-BU	Unisem Batam	UA GR			MLX92215LUA-AAA-000-BU	Lingsen,	UA GR
N/A	MLX92232LUA-AAA-000-BU	Unisem Batam	UA GR			MLX92232LUA-AAA-000-BU	Lingsen,	UA GR
N/A	MLX92232LUA-AAA-001-BU	Unisem Batam	UA GR			MLX92232LUA-AAA-001-BU	Lingsen,	UA GR
N/A	MLX92232LUA-AAA-002-BU	Unisem Batam	UA GR			MLX92232LUA-AAA-002-BU	Lingsen,	UA GR
N/A	MLX92232LUA-AAA-003-BU	Unisem Batam	UA GR			MLX92232LUA-AAA-003-BU	Lingsen,	UA GR
N/A	MLX92292LUA-AAA-000-BU	Unisem Batam	UA GR			MLX92292LUA-AAA-000-BU	Lingsen,	UA GR
N/A	MLX91209LVA-CAA-000-CR	Unisem Batam	VA GR			MLX91209LVA-CAA-000-CR	Lingsen,	VA GR
N/A	MLX91209LVA-CAA-001-BU	Unisem Batam	VA GR			MLX91209LVA-CAA-001-BU	Lingsen,	VA GR
N/A	MLX91209LVA-CAA-001-CR	Unisem Batam	VA GR			MLX91209LVA-CAA-001-CR	Lingsen,	VA GR
N/A	MLX91209LVA-CAA-002-BU	Unisem Batam	VA GR			MLX91209LVA-CAA-002-BU	Lingsen,	VA GR
N/A	MLX91209LVA-CAA-002-CR	Unisem Batam	VA GR			MLX91209LVA-CAA-002-CR	Lingsen,	VA GR
N/A	MLX91217LVA-ABA-001-BU	Unisem Batam	VA GR			MLX91217LVA-ABA-001-BU	Lingsen,	VA GR
N/A	MLX91217LVA-ABA-001-CR	Unisem Batam	VA GR			MLX91217LVA-ABA-001-CR	Lingsen,	VA GR





