



Customer Information Notification

202104025I : NXP Final Test Site Relocation Initiative: ATTJ to ATTJ Building 2 (ATTJ-B2) - Phase 2

Note: This notice is NXP Company Proprietary.

Issue Date: Apr 20, 2021 **Effective date:** May 21, 2021

Here is your personalized notification about a NXP general announcement.
For detailed information we invite you to view this notification online

Change Category

<input type="checkbox"/> Wafer Fab Process	<input type="checkbox"/> Assembly Process	<input type="checkbox"/> Product Marking	<input type="checkbox"/> Test Process	<input type="checkbox"/> Design
<input type="checkbox"/> Wafer Fab Materials	<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Equipment	<input type="checkbox"/> Errata
<input type="checkbox"/> Wafer Fab Location	<input type="checkbox"/> Assembly Location	<input type="checkbox"/> Packing/Shipping/Labeling	<input checked="" type="checkbox"/> Test Location	<input type="checkbox"/> Electrical spec./Test coverage
<input type="checkbox"/> Firmware	<input type="checkbox"/> Other			

PCN Overview

Description

NXP Semiconductors announces the ATTJ Final Test Site Relocation Initiative from the current NXP ATTJ, Tianjin, China test site to local, nearby (2.5km away) ATTJ-B2 test site, creating a consolidated ATTJ Test Center of Excellence. The associated Test Backend Shipping / Packing Operations relocate to the ATTJ-B2 site as well.

This NXP Initiative is a phased / ramped relocation activity, until all Final Test platform types have been relocated to the ATTJ-B2.

This major, strategic NXP initiative ensures future scalability of NXP ATTJ backend manufacturing sites, ATTJ main factory and new ATTJ-B2, to support current and future business. The current ATTJ main factory manufacturing floor space is fully utilized. Final Test and Test Backend Shipping / Packing Operations must be migrated to the new ATTJ-B2 Test Center of Excellence, while the existing ATTJ main factory will be exclusive for assembly and other non-Final Test operations. This initiative allows growth opportunities for both ATTJ manufacturing buildings for customer supply assurance.

The ATTJ-B2 is located 2.5 km Southeast from the current ATTJ main factory site, and adheres to the same ATTJ criteria: 100k clean room rating, temperature / humidity / ESD controls, and quality accreditations.

All current ATTJ main factory Final Test equipment (hardware / software), test flows, test programs, policies, procedures, and personnel will be relocated to the new ATTJ-B2. Absolutely no impact to product form, fit, function or reliability.

Please see the attached documents for additional details, including Qualification Results.

Reason

Qualification of NXP ATTJ, Tianjin, China new ATTJ-B2 is a new NXP strategic initiative to create a consolidated ATTJ Test Center of Excellence for Final Test Site and associated Test Backend Shipping / Packing Operations for current and future customer supply assurance.

Identification of Affected Products

Product identification does not change

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No Impact on form, fit, function, reliability or quality

Disposition of Old Products

Existing inventory will be shipped until depleted

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply .

NXP Semiconductors
High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006- 2021 NXP Semiconductors. All rights reserved.

Affected OPNs	12NC	Affected OPNs	12NC	Affected OPNs	12NC
MCF5253CVM140	935325229557	MIMXRT1052CVL5B	935365841557	MCIMX6Z0DVM09ABR	935377904518
MCF5253VM140	935309492557	MIMXRT1052CVL5BR	935365841518	MIMXRT1176CVM8A	935416204557
MCF5251VM140	935313611557	MIMXRT1052DVL6A	935351124557	MIMXRT1176DVMAA	935416205557
MCIMX6G2CVK05AB	935346139557	MIMXRT1052DVL6B	935365842557	MIMXRT1171CVM8A	935416773557
MCIMX6G1CVM05AB	935346153557	MIMXRT1052DVL6BR	935365842518	MIMXRT1171DVMAA	935416774557
MCIMX6G1CVM05ABR	935346153518	MIMXRT1051CVJ5B	935383268557	MIMXRT1172CVM8A	935416776557
MCIMX6G2CVM05AB	935346156557	MIMXRT1051DVJ6B	935376003557	MIMXRT1172DVMAA	935416777557
MCIMX6G2CVM05ABR	935346156518	MIMXRT1052CVJ5B	935376004557	MIMXRT1173CVM8A	935416778557
MCIMX6G2DVK05AB	935346141557	MIMXRT1052DVJ6B	935376005557	MIMXRT1175CVM8A	935416781557
MCIMX6G0DVM05AB	935346149557	MCIMX502CVK8B	935323228557	MIMXRT1175DVMAA	935416782557
MCIMX6G0DVM05ABR	935346149518	MCIMX507CVK8B	935323331557	MIMXRT1165CVM5A	935421516557
MCIMX6G2DVM05AB	935346157557	MCIMX507CVK8BR2	935323331518	MIMXRT1165DVM6A	935421517557
MC9328MX21CJM	935317143557	MCIMX508CVK1B	935315263557	MIMXRT1166CVM5A	935421518557
MC9328MX21CJMR2	935317143518	MCIMX508CVK8B	935317367557	MIMXRT1166DVM6A	935421519557
MC9328MX21CVM	935319088557	MCIMX508CVK8BR2	935317367518	MIMXRT117FCVM8A	935421522557
MC9328MX21CVMR2	935319088518	MCIMX502CVM8B	935323164557	MIMXRT117FDVMAA	935421523557
MC9328MX21DVM	935313584557	MCIMX502EVM8B	935314702557	MIMXRT117HCVM8A	935421525557
MC9328MX21SCVM	935322669557	MCIMX503CVM8B	935324434557	MIMXRT117HDVMAA	935421526557
MC9328MX21SVM	935324022557	MCIMX507CVM1B	935319936557	MIMX8MN5DVPIZAA	935419701557
MC9328MX21VM	935309702557	MCIMX507CVM1BR2	935319936518	MIMX8MN5CVPIZAA	935419699557
MC9328MX21VMR2	935309702518	MCIMX507CVM8B	935319785557	MIMX8MN3DVPIZAA	935421604557
MC9328MX21CVK	935316662557	MCIMX508CVM8B	935324415557	MIMX8MN3CVPIZAA	935421603557
MC9328MX21DVK	935322225557	MCIMX508CVM8BR2	935324415518	MIMX8MN1DVPIZAA	935421602557
MC9328MX21SCVK	935313585557	MCIMX515DVK8C	935317113557	MIMX8MN1CVPIZAA	935421601557
MC9328MX21SCVKR2	935313585518	MCIMX512CJM6C	935324332557	MIMX8ML8DVNLZAB	935416737557
MC9328MX21SVK	935309386557	MCIMX512CJM6CR2	935324332518	MIMX8ML6DVNLZAB	935416735557
MC9328MX21VK	935309396557	MCIMX513CJM6C	935319533557	MIMX8ML4DVNLZAB	935416733557
MCIMX250CJM4A	935323368557	MCIMX515CJM6C	935317157557	MIMX8ML3DVNLZAB	935416731557
MCIMX257CJM4A	935314249557	MCIMX515CJM6CR2	935317157518	MIMX8ML8CVNKZAB	935416736557
MCIMX250DJM4A	935319662557	MCIMX512DJM8C	935324331557	MIMX8ML6CVNKZAB	935416734557
MCIMX250DJM4AR2	935319662518	MCIMX513DJM8C	935324333557	MIMX8ML4CVNKZAB	935416732557
MCIMX253DJM4A	935319592557	MCIMX515DJM8C	935319544557	MIMX8ML3CVNKZAB	935416729557
MCIMX257DJM4A	935310307557	MCIMX515DJM8CR2	935319544518	KIMX8MM5DVTLZDA	935406972557
MCIMX257DJM4AR2	935310307518	SCIMX051DJM8C	935314553557	MCIMX535DVP1C2	935420971557
MCIMX250CJM4A	935324402557	MCIMX6V2CVM08AB	935346039557	MCIMX535DVP1C2R2	935420971518
MCIMX253CJM4A	935310306557	MCIMX6V7DVN10AA	935332463557	MCIMX535DVP2C2	935420972557
MCIMX257CJM4A	935310512557	MCIMX6V7DVN10AB	935345954557	MCIMX537CVP8C2	935420974557
MCIMX257CJM4AR2	935310512518	MCIMX6Y1CVK05AA	935326082557	MCIMX537CVP8C2R2	935420974518
MCIMX258CJM4A	935315863557	MCIMX6Y1CVK05AB	935357243557	MCIMX7U3CVP06SD	935402112557
MCIMX258CJM4AR2	935315863518	MCIMX6Y2CVK05AA	935316312557	MCIMX7U3DVK07SD	935402105557
MCIMX258CVM4	935323054557	MCIMX6Y2CVK08AB	935357246557	MCIMX7U5CVP06SD	935402113557
MCIMX27LVOP4A	935312302557	MCIMX6Y0CVM05AA	935332946557	MCIMX7U5DVK07SD	935402106557
MCIMX27LVOP4AR2	935312302518	MCIMX6Y0CVM05AB	935357241557	MCIMX7U5DVP07SD	935402114557
MCIMX27VJP4A	935310156557	MCIMX6Y1CVM05AB	935354638557	MIMX8DX5CVLFZAC	935407705557
MCIMX27VOP4A	935309882557	MCIMX6Y2CVM05AA	935318725557	MIMX8DX5GVLFZAC	935409294557
MCIMX27VOP4AR2	935309882518	MCIMX6Y2CVM05AAR	935318725518	MIMX8DX6CVLFZAC	935407706557

Affected OPNs	12NC	Affected OPNs	12NC	Affected OPNs	12NC
MCIMX27LMJP4A	935325488557	MCIMX6Y2CVM05AB	935357247557	MIMX8DX6GVLFZAC	935409295557
MCIMX27LMOP4A	935315014557	MCIMX6Y2CVM05ABR	935357247518	MIMX8MN2CVTIZAAR	935391874518
MCIMX27LMOP4AR2	935315014518	MCIMX6Y2CVM08AA	935340995557	MIMX8QX5CVLFZAC	935407707557
MCIMX27MJP4A	935310155557	MCIMX6Y2CVM08AB	935357248557	MIMX8QX5GVLFZAC	935409296557
MCIMX27MJP4AR2	935310155518	MCIMX6Y1DVK05AA	935332944557	MIMX8QX6CVLFZAC	935407708557
MCIMX27MOP4A	935309919557	MCIMX6Y1DVK05AB	935357244557	MIMX8QX6GVLFZAC	935409297557
MCIMX27MOP4AR2	935309919518	MCIMX6Y2DVK09AB	935357249557	MIMX8UX5CVLFZAC	935407702557
MCIMX280CVM4B	935323113557	MCIMX6Y7DVK05AA	935322485557	MIMX8UX5GVLFZAC	935409298557
MCIMX280CVM4BR2	935323113518	MCIMX6Y7DVK05AB	935357253557	MIMX8UX6CVLFZAC	935407703557
MCIMX280CVM4C	935369795557	MCIMX6Y7DVK10AA	935340996557	MIMX8UX6GVLFZAC	935409299557
MCIMX280CVM4CR2	935369795518	MCIMX6Y1DVM05AB	935357245557	MIMXRT1015CAF4AR	935380892528
MCIMX283CVM4B	935323027557	MCIMX6Y2DVM05AA	935313074557	MIMXRT1051CVJ5BR	935383268518
MCIMX283CVM4BR2	935323027518	MCIMX6Y2DVM05AAR	935313074518	MIMXRT105SCVL5B	935420436557
MCIMX283CVM4C	935369789557	MCIMX6Y2DVM05AB	935357251557	MIMXRT105SDVL6B	935420437557
MCIMX283CVM4CR2	935369789518	MCIMX6Y2DVM09AA	935346022557	MIMXRT106ACVL5B	935414459557
MCIMX286CVM4B	935317889557	MCIMX6Y2DVM09AB	935357252557	MIMXRT106FCVL5B	935414461557
MCIMX286CVM4BR2	935317889518	MCIMX6Y7DVM09AA	935346023557	MIMXRT106LCVL5B	935414462557
MCIMX286CVM4C	935369793557	MCIMX6Y7DVM09AB	935357254557	MIMXRT106SCVL5B	935420438557
MCIMX286CVM4CR2	935369793518	MCIMX6Z0DVM09AB	935377904557	MIMXRT533SFFOC	935416243557
MCIMX287CVM4B	935314282557	MCIMX6Z0DVM09ZZ	935377599557	MIMXRT533SFFOCR	935416243518
MCIMX287CVM4C	935369802557	MIMXRT1011CAE4A	935389372557	MIMXRT555SFFOC	935416244557
MCIMX280DVM4B	935325577557	MIMXRT1011DAE5A	935389373557	MIMXRT555SFFOCR	935416244518
MCIMX280DVM4BR	935325577518	MIMXRT1015CAF4A	935380892557	MIMXRT595SFFOB	935402846557
MCIMX280DVM4C	935369765557	MIMXRT1015CAF4B	935396794557	MIMXRT595SFFOBR	935402846518
MCIMX280DVM4CR	935369765518	MIMXRT1015DAF5A	935380893557	MIMXRT595SFFOC	935416245557
MCIMX283DVM4B	935314285557	MIMXRT1015DAF5B	935396795557	MIMXRT595SFFOCR	935416245518
MCIMX283DVM4BR2	935314285518	MIMXRT1021CAF4A	935360317557	SIMX8UX1CVLFZAC	935407701557
MCIMX283DVM4C	935369797557	MIMXRT1021CAF4B	935396796557	SIMX8UXZCVLFZAC	935407704557
MCIMX283DVM4CR2	935369797518	MIMXRT1021DAF5A	935360319557	MIMXRT1165XVM5A	935424213557
MCIMX286DVM4B	935312782557	MIMXRT1021DAF5B	935396799557	MIMXRT1166XVM5A	935424214557
MCIMX286DVM4BR	935312782518	MIMXRT1021CAG4A	935360318557	MC34932EKR2	935315126518
MCIMX286DVM4C	935369799557	MIMXRT1021CAG4AR	935360318528	MC34932EK	935315126574
MCIMX286DVM4CR	935369799518	MIMXRT1021CAG4B	935396798557	MC34931EK	935311557574
MCIMX31CJKN5D	935321414557	MIMXRT1021CAG4BR	935396798528	MC17XSF500EKR2	934070624518
MCIMX31CVKN5D	935314015557	MIMXRT1021DAG5A	935360321557	MC17XSF500EK	934070624574
MCIMX31DVKN5D	935319446557	MIMXRT1021DAG5B	935396801557	MC16XSD200FK	934070599557
MCIMX31DVMN5D	935321333557	MIMXRT1061CVL5A	935373201557	MC07XSC200EKR2	934070625518
MCIMX31LCVKN5D	935322884557	MIMXRT1061CVL5B	935394376557	MC07XSC200EK	934070625574
MCIMX31LCVKN5DR2	935322884518	MIMXRT1061DVL6A	935373202557	MPF5020AMNA0EP	935400432557
MCIMX31LDVKN5D	935314018557	MIMXRT1061DVL6B	935388058557	MPF5020AMNA0EPR2	935400433528
MCIMX31LDVKN5DR2	935314018518	MIMXRT1062CVL5A	935373203557	MPF5023AMNA0EPR2	935399862528
MCIMX31LDVMN5D	935317023557	MIMXRT1062CVL5B	935394381557	MPF5023AMNA0EP	935399862557
MCIMX31LDVMN5DR2	935317023518	MIMXRT1062DVL6A	935373204557	MC13892CJVLR2	935317536518
MCIMX353CJQ5C	935325487557	MIMXRT1062DVL6B	935394383557	MC13892CJVL	935317536557
MCIMX353CVM5B	935324376557	MIMXRT1061CVJ5A	935379986557	MC13892DJVL	935311099557
MCIMX357CJQ5C	935314143557	MIMXRT1061CVJ5AR	935379986518	MC13892DJVLR2	935311099518

Affected OPNs	12NC	Affected OPNs	12NC	Affected OPNs	12NC
MCIMX357CJQ5CR2	935314143518	MIMXRT1061CVJ5B	935394375557	MC32PF3000A8EP	935320745557
MCIMX357CVM5B	935324286557	MIMXRT1061DVJ6A	935386102557	MC34PF3000A8EP	935344309557
MCIMX353DJQ5C	935310163557	MIMXRT1061DVJ6B	935394377557	MC32PF3000A8EPR2	935320745528
MCIMX353DJQ5CR2	935310163518	MIMXRT1062CVJ5A	935379987557	MC34PF3000A8EPR2	935344309528
MCIMX353DVM5B	935314056557	MIMXRT1062CVJ5AR	935379987518	MC33PF3000A3ESR2	935322443528
MCIMX357DJQ5C	935310182557	MIMXRT1062CVJ5B	935394379557	MC33PF3000A5ESR2	935316316528
MCIMX357DJQ5CR2	935310182518	MIMXRT1062DVJ6A	935379988557	MC33PF3000A5ES	935316316557
MCIMX357DVM5B	935317293557	MIMXRT1062DVJ6B	935394382557	MC33PF3000A6ESR2	935318792528
MCIMX357DVM5BR2	935317293518	MIMXRT1064CVL5A	935377468557	MC33PF3000A7ESR2	935318793528
SCIMX6X3EVK10ABR	935315801518	MIMXRT1064CVL5B	935399267557	MC33PF3000A0ESR2	935318758528
KCIMX6X1CVK08AB	935316107557	MIMXRT1064DVL6A	935377469557	MC33PF3000A4ES	935313089557
MCIMX6X1CVK08AB	935316106557	MIMXRT1064DVL6AR	935377469518	MC33PF3000A0ES	935318758557
MCIMX6X1CVK08AC	935354468557	MIMXRT1064DVL6B	935399271557	MC33PF3001A6ES	935316245557
MCIMX6X1CVO08AB	935312942557	MIMXRT1064DVL6BR	935399271518	MC33PF3001A7ESR2	935313087528
MCIMX6X1CVO08ABR	935312942518	MIMXRT1064CVJ5A	935396434557	MC33PF3001A7ES	935313087557
MCIMX6X1CVO08AC	935361033557	MIMXRT1064CVJ5B	935399266557	MC34PF3001A7EP	935315951557
MCIMX6X1CVO08ACR	935361033518	MIMXRT1064DVJ6A	935396435557	MC34PF3001A5EPR2	935318606528
MCIMX6X2CVN08AB	935322176557	MIMXRT1064DVJ6B	935399268557	MC32PF3001A6EPR2	935312927528
MCIMX6X2CVN08AC	935363895557	K32H844P000VMUAR	935332986518	MC34PF3001A2EPR2	935320654528
MCIMX6X3CVN08AB	935315797557	K32H844P000VMUAT	935332986557	MC32PF3001A2EP	935320741557
MCIMX6X3CVN08AC	935363896557	MC56F8014MFAE	935310004557	MC32PF3001A4EPR2	935312882528
MCIMX6X3CVO08AB	935318479557	MC56F8011VFAE	935325159557	MC32PF3001A1EPR2	935320703528
MCIMX6X3CVO08AC	935354471557	MC56F8013MFAE	935322601557	MC32PF3001A3EP	935313015557
MCIMX6X4CVM08AB	935311959557	MC56F8013VFAE	935316569557	MC34PF3001A6EP	935312672557
MCIMX6X4CVM08AC	935354439557	MC56F8013VFAER2	935316569528	MC34PF3001A4EPR2	935324942528
MCIMX6X1EVK10AB	935312236557	MC56F8014VFAE	935320973557	MC32PF3001A2EPR2	935320741528
MCIMX6X1EVK10AC	935363027557	MC56F8245MLD	935321962557	MC34PF3001A4EP	935324942557
MCIMX6X3CVK08AB	935315942557	MC56F8245VLD	935323371557	MC32PF3001A5EP	935318654557
MCIMX6X3CVK08AC	935359418557	MC56F8246MLF	935317808557	MC32PF3001A1EP	935320703557
MCIMX6X3CVK08ACR	935359418518	MC56F8246MLFR	935317808528	MC34PF3001A3EPR2	935315937528
MCIMX6X3EVK10AB	935315799557	MC56F8246VLF	935321556557	MC32PF3001A4EP	935312882557
MCIMX6X3EVK10ABR	935315799518	MC56F8246VLFR	935321556528	MC34PF3001A2EP	935320654557
MCIMX6X3EVK10AC	935353847557	MC56F8247MLH	935314948557	MC32PF3001A7EPR2	935318562528
MCIMX6X3EVK10ACR	935353847518	MC56F8247VLH	935319676557	MC34PF3001A3EP	935315937557
MCIMX6X1EVO10AB	935315224557	MC56F8247VLHR	935319676528	MC34PF3001A1EPR2	935322352528
MCIMX6X1EVO10AC	935363893557	MC56F8255MLD	935310531557	MC32PF3001A6EP	935312927557
MCIMX6X2EVN10AB	935320463557	MC56F8255VLD	935321557557	MC34PF3001A6EPR2	935312672528
MCIMX6X2EVN10ABR	935320463518	MC56F8256MLF	935315367557	MC32PF4210A2ESR2	935369026528
MCIMX6X2EVN10AC	935353853557	MC56F8256VLF	935310528557	MC32PF4210A1ES	935353765557
MCIMX6X3EVN10AB	935320375557	MC56F8257MLH	935314294557	MC34PF4210A2ESR2	935369037528
MCIMX6X3EVN10AC	935363897557	MC56F8257MLHR	935314294528	MC34PF4210A1ESR2	935353959528
MCIMX6X3EVO10AB	935323679557	MC56F8257VLH	935314406557	MC32PF4210A1ESR2	935353765528
MCIMX6X3EVO10AC	935363898557	MC56F8023VLC	935320974557	MC34PF4210A2ES	935369037557
MCIMX6X4EVM10AB	935318213557	MC56F8023VLCR	935320974528	MC34PF4210A0ESR2	935355113528
MCIMX6X4EVM10AC	935363025557	MC56F8025VLD	935311623557	MC34PF4210A4ESR2	935376938528
MCIMX6D7CVT08AC	935319926557	MC56F8025VLDR	935311623528	MC34PF4210A0ES	935355113557

Affected OPNs	12NC	Affected OPNs	12NC	Affected OPNs	12NC
MCIMX6D7CVT08AD	935315236557	MC56F8027VLH	935314082557	MC34PF4210A4ES	935376938557
MCIMX6D5EYM10AC	935323467557	MC56F8027VLHR	935314082528	MC32PF4210A0ES	935353632557
MCIMX6D5EYM10ACR	935323467518	MC56F8033VLC	935315541557	MC34PF4210A3ES	935369039557
MCIMX6D5EYM10AD	935315182557	MC56F8035VLD	935315324557	MC34PF4210A3ESR2	935369039528
MCIMX6D5EYM10ADR	935315182518	MC56F8035VLDR	935315324528	MC32PF4210A4ES	935376928557
MCIMX6D5EZK08AD	935323611557	MC56F8036VLF	935323599557	MC32PF4210A3ESR2	935369035528
MCIMX6D5EZK08AE	935357853557	MC56F8037MLH	935324848557	MC34PF4210A1ES	935353959557
MCIMX6D5EZK10AE	935357854557	MC56F8037VLH	935323055557	MC32PF4210A4ESR2	935376928528
MCIMX6U7CVM08AB	935312063557	MC56F8037VLHR	935323055528	MC34VR5100A2EPR2	935313347528
MCIMX6U7CVM08AC	935314935557	SC56F8037F4VLH	935325515557	MC34VR5100A2EP	935313347557
MCIMX6U5DVM10AB	935317963557	MC56F8322MFAE	935313445557	MC34VR5100A1EPR2	935313158528
MCIMX6U5DVM10ABR	935317963518	MC56F8323MFBE	935313457557	MC34VR5100A0EP	935315851557
MCIMX6U5DVM10AC	935323455557	MC56F8122VFAE	935320975557	MC34VR5100A0EPR2	935315851528
MCIMX6U5DVM10ACR	935323455518	MC56F8123VFBE	935313443557	MC13892CJVK	935312979557
MCIMX6U8DVM10AB	935314819557	MC56F8322VFAE	935316577557	MC13892DJVKR2	935321856518
MCIMX6U8DVM10AC	935315821557	MC56F8322VFAER2	935316577528	MC13892DJVK	935321856557
MCIMX6U5EVM10AB	935317882557	MC56F8323VFBE	935309359557	MC13892CJVKR2	935312979518
MCIMX6U5EVM10ABR	935317882518	MC56F8323VFBER	935309359528	MC34825EPR2	935320466528
MCIMX6U5EVM10AC	935324722557	MCR20AVHM	935318183557	MC34VR500VBESR2	935380387528
MCIMX6U5EVM10ACR	935324722518	MC56F8357MPYE	935322605557	MC34VR500V4ESR2	935320767528
MCIMX6DP5EVT2AA	935337523557	MC56F8155VFGE	935309357557	MC34VR500V9ES	935373754557
MCIMX6DP5EVT2AB	935363577557	MC56F8157VPYE	935318989557	MC34VR500VAES	935377258557
MCIMX6DP7CVT8AA	935315902557	MC56F8355MFGE	935313444557	MC34VR500V8ESR2	935313052528
MCIMX6DP7CVT8AB	935356639557	MC56F8355VFGE	935320991557	MC34VR500V3ES	935315337557
MCIMX6DP5EYM1AA	935316005557	MC56F8357VPYE	935322606557	MC34VR500VAESR2	935377258528
MCIMX6DP5EYM1AB	935357835557	MC13234CHT	935310615557	MC34VR500V7ES	935320792557
MCIMX6Q7CVT08AC	935311044557	MC13234CHTR	935310615518	MC34VR500V1ES	935315493557
MCIMX6Q7CVT08AD	935324758557	MC13237CHT	935311049557	MC34VR500V7ESR2	935320792528
MCIMX6Q7CVT08AE	935354334557	MC13237CHTR	935311049518	MC34VR500V6ESR2	935318678528
MCIMX6D5EYM12AC	935323278557	MC11E1CPBE2	935325144557	MC34VR500V3ESR2	935315337528
MCIMX6D5EYM12AD	935311654557	MC705C8ACFBE	935325158557	MC34VR500VBES	935380387557
MCIMX6D5EYM10CE	935357866557	MCHSC705C8ACFBE	935325191557	MC34VR500V9ESR2	935373754528
MCIMX6D5EYM12AE	935357867557	SC705C8AE0VFBE	935314598557	MC34VR500V1ESR2	935315493528
MCIMX6D5EYM12CE	935357868557	MC705P6ACDWE	935309329574	MC34VR500V5ES	935316272557
MCIMX6Q5EYM10AC	935314761557	MC705P6AMDWE	935316546574	MC34VR500V2ES	935318158557
MCIMX6Q5EYM10ACR	935314761518	MC705P6AMDWER	935316546518	MC34VR500V8ES	935313052557
MCIMX6Q5EYM10AD	935321953557	MC908JB8FBE	935316862557	MC34708VMR2	935310717518
MCIMX6Q5EYM10ADR	935321953518	MC908JB8JDWE	935312374574	MC34708VM	935310717557
MCIMX6Q5EYM10AE	935357869557	MC56F8365MFGE	935316578557	MC34708VKR2	935319753518
MCIMX6Q5EYM10AER	935357869518	MC56F8367MPYE	935320997557	MC34708VK	935319753557
MCIMX6Q5EYM10CE	935357872557	MC56F8165VFGE	935320987557	MC34GD3000EP	935313159557
MCIMX6Q5EYM12AC	935319908557	MC56F8167VPYE	935309348557	MC34GD3000EPR2	935313159528
MCIMX6Q5EYM12AD	935323494557	MC56F8365VFGE	935313462557	MC34717EP	935318977557
MCIMX6Q5EYM12AE	935357873557	MC56F8367VPYE	935316582557	MC34717EPR2	935318977528
MCIMX6Q5EYM12CE	935357874557	MIMX8MD6CVAHZAA	935358607557	MC34716EP	935313896557
MCIMX6D7CZK08AD	935315782557	MIMX8MD6CVAHZAB	935377781557	MC34716EPR2	935313896528

Affected OPNs	12NC	Affected OPNs	12NC	Affected OPNs	12NC
MCIMX6D7CZK08AE	935354328557	MIMX8MD6DVAJZAA	935358608557	MC34704BEP	935315635557
MCIMX6Q5EZK08AD	935312405557	MIMX8MD6DVAJZAB	935377775557	MC34704BEPR2	935315635528
MCIMX6Q5EZK08AE	935362212557	MIMX8MD7CVAHZAA	935358609557	MC34704AEPR2	935312365528
MCIMX6Q5EZK10AE	935357855557	MIMX8MD7CVAHZAB	935377782557	MC34700EP	935313967557
MCIMX6Q7CZK08AD	935315667557	MIMX8MD7DVAJZAA	935358611557	MC34700EPR2	935313967528
MCIMX6Q7CZK08AE	935354329557	MIMX8MD7DVAJZAB	935377783557	MC34713EP	935315459557
MCIMX6QP5EVT2AA	935337524557	MIMX8MQ5CVAHZAA	935358612557	MC34713EPR2	935315459528
MCIMX6QP5EVT2AB	935363581557	MIMX8MQ5CVAHZAB	935377776557	MC33913AE	935323381557
MCIMX6QP7CVT8AA	935312744557	MIMX8MQ5DVAJZAA	935358613557	MC33913AER2	935323381528
MCIMX6QP7CVT8AB	935356641557	MIMX8MQ5DVAJZAB	935377777557	MC34913AER2	935314922528
MCIMX6QP5EYM1AA	935316001557	MIMX8MQ6CVAHZAA	935358614557	MC34913AE	935314922557
MCIMX6QP5EYM1AB	935357836557	MIMX8MQ6CVAHZAB	935377778557	SC900665EPR2	935309813528
MCIMX6S7CVM08AB	935317691557	MIMX8MQ6DVAJZAA	935358615557	SC900665EP	935309813557
MCIMX6S7CVM08AC	935311754557	MIMX8MQ6DVAJZAB	935377779557	MCZ34670EG	935316769574
MCIMX6S7CVM08ACR	935311754518	MIMX8MQ6DVAJZIB	935395873557	MCZ34670EGR2	935316769518
MCIMX6S5DVM10AB	935311117557	MIMX8MQ7CVAHZAA	935358616557	SC900666AKR2	935322215528
MCIMX6S5DVM10ABR	935311117518	MIMX8MQ7CVAHZAB	935377784557	SC900666AK	935322215557
MCIMX6S5DVM10AC	935320221557	MIMX8MQ7DVAJZAA	935358617557	MC34937APEKR2	935323431518
MCIMX6S5DVM10ACR	935320221518	MIMX8MQ7DVAJZAB	935377785557	MC34937APEK	935323431574
MCIMX6S8DVM10AB	935323313557	MCF54415CMJ250	935324396557	MC34844AEPR2	935311717528
MCIMX6S8DVM10AC	935320293557	MCF54417CMJ250	935318146557	MC34845DEP	935314226557
MCIMX6S5EVM10AB	935317895557	MCF54416CMJ250	935310465557	MC34845DEPR2	935314226528
MCIMX6S5EVM10ABR	935317895518	MCF54418CMJ250	935313113557	MC34845CEP	935310255557
MCIMX6S5EVM10AC	935311756557	MCF54418CMJ250R	935313113518	MC34845CEPR2	935310255528
MCIMX6S5EVM10ACR	935311756518	MC56F8335MFGE	935323954557	MMPF0100FCANES	935340925557
MCIMX6S5EVM10AD	935360463557	MC56F8345MFGE	935316573557	MMPF0100FBANES	935331621557
MCIMX6L2DVN10AB	935321896557	MC56F8135VFGE	935316557557	MMPF0100FCANESR2	935340925528
MCIMX6L2DVN10AC	935360493557	MC56F8145VFGE	935309356557	MMPF0100FCAEPR2	935336039528
MCIMX6L2EVN10AB	935315744557	MC56F8335VFGE	935318991557	MMPF0100FDAEP	935340782557
MCIMX6L2EVN10ABR	935315744518	MC56F8335VFER	935318991518	MMPF0100FCAEP	935336039557
MCIMX6L2EVN10AC	935360494557	MC56F8345VFGE	935325161557	MC34PF1510A3EP	935371924557
MCIMX6L2EVN10ACR	935360494518	MC12311CHN	935323222557	MC34PF1510A0EPR2	935405832528
MCIMX6L3DVN10AB	935323421557	MC12311CHNR	935323222518	MC32PF1510A3EPR2	935371715528
MCIMX6L3DVN10AC	935360495557	MKW01Z128CHN	935324621557	MC34PF1510A1EPR2	935371928528
MCIMX6L3EVN10AB	935317907557	MKW01Z128CHNR	935324621518	MC32PF1510A6EP	935371869557
MCIMX6L3EVN10AC	935360496557	MC13201FC	935318954557	MC34PF1510A4EP	935371922557
MCIMX6L7DVN10AB	935321922557	MC13201FCR2	935318954528	MC34PF1510A5EP	935371919557
MCIMX6L7DVN10AC	935360497557	MC13202FC	935318586557	MC34PF1510A4EPR2	935371922528
MCIMX6L8DVN10AA	935311127557	MC13202FCR2	935318586528	MC34PF1510A3EPR2	935371924528
MCIMX6L8DVN10AB	935321842557	MC13211	935309323557	MC32PF1510A0EPR2	935404098528
MCIMX6L8DVN10ABR	935321842518	MC13211R2	935309323518	MC32PF1510A4EPR2	935371717528
MCIMX6L8DVN10AC	935352982557	MC13212	935313421557	MC34PF1510A6EPR2	935371917528
MCIMX6L8DVN10ACR	935352982518	MC13212R2	935313421518	MC32PF1510A1EPR2	935371912528
SCIMX6L8DVN10AB	935321843557	MC13213	935313422557	MC32PF1510A2EPR2	935371713528
MCIMX537CVV8C	935319782557	MC13213R2	935313422518	MC32PF1510A7EPR2	935371867528
MCIMX537CVV8C2	935318276557	MIMX8MN1CVTHZAA	935396097557	MC32PF1510A3EP	935371715557

Affected OPNs	12NC	Affected OPNs	12NC	Affected OPNs	12NC
MCIMX537CVV8C2R2	935318276518	MIMX8MN1CVTIZAA	935391873557	MC32PF1510A6EPR2	935371869528
MCIMX537CVV8CR2	935319782518	MIMX8MN1DVTJZAA	935390505557	MC32PF1510A7EP	935371867557
MCIMX535DVV1C	935321916557	MIMX8MN2CVTHZAA	935396098557	MC34PF1510A5EPR2	935371919528
MCIMX535DVV1C2	935323459557	MIMX8MN2CVTIZAA	935391874557	MC32PF1510A4EP	935371717557
MCIMX535DVV1C2R2	935323459518	MIMX8MN2DVTJZAA	935391122557	MC34PF1510A1EP	935371928557
MCIMX535DVV1CR2	935321916518	MIMX8MN3CVTHZAA	935396099557	MC34PF1510A0EP	935405832557
MCIMX535DVV2C	935319813557	MIMX8MN3CVTIZAA	935391875557	MC34PF1510A7EP	935371915557
MCIMX535DVV2C2	935323583557	MIMX8MN3DVTJZAA	935390506557	MC34PF1510A2EP	935371926557
MCIMX6S7CVM08AD	935354192557	MIMX8MN4CVTHZAA	935396101557	MC32PF1510A1EP	935371912557
MCIMX6D7CVT08AE	935354333557	MIMX8MN4CVTIZAA	935391876557	MC32PF1510A0EP	935404098557
MCIMX6D5EYM10AE	935357864557	MIMX8MN4DVTJZAA	935390507557	MC32PF1550A8EPR2	935377557528
MCIMX6D5EYM10AER	935357864518	MIMX8MN5CVTHZAA	935396102557	MC32PF1550A1EP	935313164557
SC667667DVTLZAA	935381487557	MIMX8MN5CVTIZAA	935391877557	MC32PF1550A1EPR2	935313164528
MIMX8MM1CVTKZAA	935378339557	MIMX8MN5DVTJZAA	935390508557	MC32PF1550A4EP	935318807699
MIMX8MM1DVTLZAA	935378333557	MIMX8MN6CVTHZAA	935396103557	MC32PF1550A7EP	935370637557
MIMX8MM2CVTKZAA	935378341557	MIMX8MN6CVTIZAA	935391878557	MC34PF1550A1EPR2	935320821528
MIMX8MM2DVTLZAA	935378334557	MIMX8MN6DVTJZAA	935390509557	MC34PF1550A5EPR2	935371461528
MIMX8MM3CVTKZAA	935378342557	MIMX8MN6DVTJZCA	935391123557	MC34PF1550A3EP	935322411557
MIMX8MM3DVTLZAA	935378335557	MIMX8MN6DVTJZDA	935391124557	MC34PF1550A6EP	935371936557
MIMX8MM4CVTKZAA	935378343557	MCIMX7D3EVK10SC	935316442557	MC34PF1550A6EPR2	935371936528
MIMX8MM4DVTLZAA	935378336557	MCIMX7D3EVK10SD	935351917557	MC32PF1550A0EP	935316132557
MIMX8MM5CVTKZAA	935378344557	MCIMX7D5EVK10SD	935381482557	MC32PF1550A6EPR2	935370635528
MIMX8MM5DVTLZAA	935378337557	MCIMX7D5EVM10SD	935352046557	MC34PF1550A2EPR2	935318731528
MIMX8MM5DVTLZBA	935389292557	MCIMX7D7DVM10SC	935320864557	MC34PF1550A9EPR2	935381902528
MIMX8MM5DVTLZCA	935389293557	MCIMX7D7DVM10SD	935351921557	MC32PF1550A3EP	935313147557
MIMX8MM5DVTLZDA	935389294557	MCIMX7S3DVK08SC	935320865557	MC32PF1550A5EP	935370633557
MIMX8MM5DVTLZEA	935389295557	MCIMX7S3DVK08SD	935351918557	MC34PF1550A4EP	935322486699
MIMX8MM6CVTKZAA	935378345557	MCIMX7S5EVK08SC	935316443557	MC34PF1550A9EP	935381902557
MIMX8MM6DVTLZAA	935378338557	MCIMX7S5EVK08SD	935351919557	MC34PF1550A8EP	935377839557
MIMX8MM6DVTLZAAR	935378338518	MCIMX7S5EVM08SC	935313214557	MC32PF1550A2EPR2	935313148528
MCIMX6U5DVM10AD	935360464557	MCIMX7S5EVM08SD	935351922557	MC32PF1550A3EPR2	935313147528
MCIMX6U5DVM10ADR	935360464518	MIMXRT1061CVJ5BR	935394375518	MC32PF1550A2EP	935313148557
MCIMX6U5EVM10AD	935360465557	MIMXRT1062CVJ5BR	935394379518	MC32PF1550A6EP	935370635557
MCIMX6U8DVM10AD	935360466557	MCIMX6G3CVK05AB	935346142557	MC32PF1550A5EPR2	935370633528
MCIMX6U5EVM10ADR	935360465518	MCIMX6G3CVM05AB	935346158557	MC34PF1550A3EPR2	935322411528
MCIMX6U7CVM08AD	935354193557	MCIMX6G3DVK05AB	935346143557	MC34PF1550A5EP	935371461557
MCIMX6S5DVM10AD	935360456557	MCIMX6G3DVM05AB	935346159557	MC34PF1550A0EP	935316139557
MCIMX6S5DVM10ADR	935360456518	MIMXRT106ADVL6A	935385521557	MC34PF1550A7EPR2	935371934528
MCIMX6S8DVM10AD	935360457557	MIMXRT106ADVL6AR	935385521518	MC32PF1550A9EPR2	935381904528
MCIMX6S5EVM10ADR	935360463518	MIMXRT106ADVL6B	935399817557	MC34PF1550A2EP	935318731557
MCIMX6S7CVM08ADR	935354192518	MIMXRT106ADVL6BR	935399817518	MC34PF1550A4EPR2	935322486697
MCIMX7U3CVP06SC	935381193557	MIMXRT106CDVL6A	935389816557	MC34PF1550A8EPR2	935377839528
MCIMX7U5CVP06SC	935381194557	MIMXRT106CDVL6B	935399818557	MC32PF1550A4EPR2	935318807697
MCIMX7U5DVP07SC	935381195557	MIMXRT106FDVL6A	935389817557	MC32PF1550A7EPR2	935370637528
MCIMX7U3DVK07SC	935381758557	MIMXRT106FDVL6B	935399819557	MC34712EP	935320492557
MCIMX7U5DVK07SC	935381759557	MIMXRT106LDVL6A	935389818557	MC34712EPR2	935320492528

Affected OPNs	12NC	Affected OPNs	12NC	Affected OPNs	12NC
MCIMX7U5DVK08SC	935381035557	MIMXRT106LDVL6B	935399821557	SC900668AKR2	935310124528
MIMXRT1051CVL5A	935351121557	MIMXRT106SDVL6A	935389819557	SC900668AK	935310124557
MIMXRT1051CVL5B	935365838557	MIMXRT106SDVL6B	935399822557	MC10XSD200FKR2	934070584578
MIMXRT1051DVL6A	935351122557	MCIMX6Y0DVM05AB	935357242557	MC10XSD200FK	934070584557
MIMXRT1051DVL6B	935365839557	MIMXRT1024CAG4A	935416162557	MC34709VK	935310974557
MIMXRT1051DVL6BR	935365839518	MIMXRT1024DAG5A	935416163557	MC34709VKR2	935310974518
MIMXRT1052CVL5A	935351123557	MCIMX6Y2DVM05ABR	935357251518		