



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: K010101

DATE: 01-Nov-2001

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1033C-803	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033C-803/T&R	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033C-902	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033C-902/T&R	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033M-10	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033M-12	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033M-15	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033M-20	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033M-25	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033M-30	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033M-8	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-10	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-10/T&R	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-12	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-12/T&R	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-15	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-15/T&R	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-20	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-25	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-25/T&R	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-25/T&R/	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-30	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-8	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-8/T&R/	N/A	30-Apr-2002	01-Nov-2003	Part can no longer be manufactured
Discontinuance	DS1033Z-T&R	N/A	30-Apr-2002	01-Nov-2003	Part is leaded. Request information on lead-free version

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Dec-2001