



# Product Change Notification

## TE Connectivity

Product Change Notification: E-20-007708

PCN Date: 17-JUN-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

Force Guided Relay SR4 & SR6 second source for contact rivets

**Description of Changes**

The following part numbers contain contact rivets, for which TE has approved an additional supplier (second source). The contacts from the additional supplier are identical in form and dimensions, in their material, as well as their manufacturing process.

**Reason for Changes:**

Manufacturing / Process Requirements. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to deliver our products on time, we've made the decision to approve an additional contact rivet supplier as a second source. This allows us to maintain production in case of a drop-out of our primary supplier. The contact rivets of both suppliers are identical in form, dimensions, material and manufacturing processes.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	19-AUG-2020
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1393260-4</a>	NO			"V23050-A1012-A542", "V23050A1012A542"			
<a href="#">1415055-1</a>	NO			"SR4D4012"			
<a href="#">3-1415018-1</a>	NO			"V23050-A1021-A533", "V23050A1021A533"			
<a href="#">3-1415054-1</a>	NO			"SR4M4048"			
<a href="#">3-1415055-1</a>	NO			"SR4D4024"			
<a href="#">3-1415353-1</a>	NO			"SR6M4024"			
<a href="#">4-1415053-1</a>	NO			"SR4M4024"			
<a href="#">5-1415019-1</a>	NO			"V23050-A1110-A551", "V23050A1110A551"			
<a href="#">5-1415053-1</a>	NO			"SR4M4005"			
<a href="#">6-1415027-1</a>	NO			"SR6D4024"			
<a href="#">6-1415053-1</a>	NO			"SR4M4006"			
<a href="#">6-1415054-1</a>	NO			"SR4M4110"			
<a href="#">6-1415055-1</a>	NO			"SR4D4048"			
<a href="#">7-1415054-1</a>	NO			"SR4D4005"			
<a href="#">8-1415053-1</a>	NO			"SR4M4012"			
<a href="#">9-1415018-1</a>	NO			"V23050-A1110-A533", "V23050A1110A533"			
<a href="#">9-1415053-1</a>	NO			"SR4M4018"			

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1393260-4</a>	NO			"V23050-A1012-A542", "V23050A1012A542"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1415055-1</a>	NO			"SR4D4012"			
<a href="#">3-1415018-1</a>	NO			"V23050-A1021-A533", "V23050A1021A533"			
<a href="#">3-1415054-1</a>	NO			"SR4M4048"			
<a href="#">3-1415055-1</a>	NO			"SR4D4024"			
<a href="#">3-1415353-1</a>	NO			"SR6M4024"			
<a href="#">4-1415053-1</a>	NO			"SR4M4024"			
<a href="#">5-1415019-1</a>	NO			"V23050-A1110-A551", "V23050A1110A551"			
<a href="#">5-1415053-1</a>	NO			"SR4M4005"			
<a href="#">6-1415027-1</a>	NO			"SR6D4024"			
<a href="#">6-1415053-1</a>	NO			"SR4M4006"			
<a href="#">6-1415054-1</a>	NO			"SR4M4110"			
<a href="#">6-1415055-1</a>	NO			"SR4D4048"			
<a href="#">7-1415054-1</a>	NO			"SR4D4005"			
<a href="#">8-1415053-1</a>	NO			"SR4M4012"			
<a href="#">9-1415018-1</a>	NO			"V23050-A1110-A533", "V23050A1110A533"			
<a href="#">9-1415053-1</a>	NO			"SR4M4018"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1393260-4</a>	NO			"V23050-A1012-A542", "V23050A1012A542"			
<a href="#">1415055-1</a>	NO			"SR4D4012"			
<a href="#">3-1415018-1</a>	NO			"V23050-A1021-A533", "V23050A1021A533"			
<a href="#">3-1415054-1</a>	NO			"SR4M4048"			
<a href="#">3-1415055-1</a>	NO			"SR4D4024"			
<a href="#">3-1415353-1</a>	NO			"SR6M4024"			
<a href="#">4-1415053-1</a>	NO			"SR4M4024"			
<a href="#">5-1415019-1</a>	NO			"V23050-A1110-A551", "V23050A1110A551"			
<a href="#">5-1415053-1</a>	NO			"SR4M4005"			
<a href="#">6-1415027-1</a>	NO			"SR6D4024"			
<a href="#">6-1415053-1</a>	NO			"SR4M4006"			
<a href="#">6-1415054-1</a>	NO			"SR4M4110"			
<a href="#">6-1415055-1</a>	NO			"SR4D4048"			
<a href="#">7-1415054-1</a>	NO			"SR4D4005"			
<a href="#">8-1415053-1</a>	NO			"SR4M4012"			
<a href="#">9-1415018-1</a>	NO			"V23050-A1110-A533", "V23050A1110A533"			
<a href="#">9-1415053-1</a>	NO			"SR4M4018"			