



Micron  
Technology,  
Inc.  
8000 S.  
Federal  
Way  
PO Box 6  
Boise, ID  
United  
States

---

## EOL of Specific SLC/MLC NAND Components

PCN: 32455

Published: 2017-08-28

---

<b>Type:</b>	End of Life
<b>Description:</b>	<p>In an effort to maximize the manufacturing efficiency for Micron's NAND product line, and to better align with industry trends, Micron will End of Life the below products.</p> <p>Please use the replacement part guidance as a first level of recommendation or reach out to your Micron contact for further assistance.</p>
<b>Reason:</b>	Better Align With Industry Standard, Manufacturing Efficiency
<b>Product Affected:</b>	Select MPNs from multiple SLC/MLC NAND designs and process nodes

---

Affected Micron Part Number	Recommended Replacement	Customer Part Number
<u>Component</u>		
MT29F128G08AEEBBH6-12:B	MT29F128G08AJAAAWP-ITZ:A	
MT29F128G08CFAAAWP-ITZ:A	MT29F128G08CFABBWP-12IT:B	
MT29F128G08CFAAAWP-Z:A	MT29F128G08CFABBWP-12IT:B	
MT29F16G08CBACAL72A3WC1-V	MT29F16G08CBACAL72A3WC1	
MT29F16G08CBACAWP-IT:C	MT29F32G08CBADBWP-12IT:D	
MT29F1G01AAADDH4:D	MT29F1G01ABAFDWB-IT:F	
MT29F1G01AAADDH4-IT:D	MT29F1G01ABAFDWB-IT:F	
MT29F1G08ABADAWP-E:D	MT29F1G08ABAFAWP-ITE:F	
<b>MT29F1G08ABAEAH4-IT:E</b>	<b>MT29F1G08ABAEAH4:E</b>	<b>557-1656-2-ND</b>
MT29F1G08ABBDAH4-IT:D	MT29F1G08ABBFAH4-ITE:F	

MT29F1G08ABBDAH4-IT:D	Contact Factory	
MT29F1G16ABBDAH4-IT:D	MT29F1G16ABBEAH4-ITX:E	
MT29F1G16ABBEAH4:E	MT29F1G16ABBEAH4-ITX:E	
MT29F1G16ABBEAH4-IT:E	MT29F1G16ABBEAH4-ITX:E	
MT29F1G16ABBEAM68M3WC2	Contact Factory	
MT29F256G08AUEDBJ6-12:D	MT29F256G08AKCBBH7-6IT:B	
MT29F256G08CJAAAWP-ITZ:A	MT29F256G08CJABBWP-12IT:B	
MT29F2G01AAAEDH4-IT:E	MT29F2G01ABAGDWB-IT:G	
MT29F2G08ABAEAWP-ATX:E	MT29F2G08ABAGAWP-IT:G	
MT29F2G08ABAEAWP-E:E	MT29F2G08ABAGAWP-ITE:G	
MT29F2G08ABBEAH4:E	MT29F2G08ABBGH4-IT:G	
<b>MT29F2G08ABBEAHC:E</b>	<b>MT29F2G08ABBGH4-IT:G</b>	<b>557-1543-2-ND</b>
<b>MT29F2G16ABAEAWP:E</b>		<b>557-1614-ND</b>
<b>MT29F2G16ABAEAWP-IT:E</b>		<b>557-1613-ND</b>
<b>MT29F2G16ABBEAH4:E</b>		<b>557-1545-2-ND</b>
MT29F2G16ABBEAH4-IT:E		
<b>MT29F2G16ABBEAHC-IT:E</b>		<b>557-1542-2-ND</b>
MT29F32G08ABEDBJ4-12:D	MT29F32G08ABCABH1-10ITZ:A	
<b>MT29F32G08AFACAWP-ITZ:C</b>	<b>Contact Factory</b>	
MT29F32G08AFACAWP-Z:C		
MT29F32G08CBACAL73A3WC1P-V	MT29F32G08CBACAL73A3WC1P	
MT29F32G08CBACAWP-ITZ:C	MT29F32G08CBADBWP-12IT:D	
MT29F4G08ABADAH4-AT:D		
MT29F4G08ABADAWP-E:D	Contact Factory	
MT29F4G16ABADAH4-AAT:D	MT29F4G16ABADAH4-AIT:D	
MT29F4G16ABADAH4-IT:D	Contact Factory	
<b>MT29F4G16ABADAWP:D</b>	<b>Contact Factory</b>	<b>557-1461-2-ND</b>
<b>MT29F4G16ABADAWP-IT:D</b>	<b>Contact Factory</b>	<b>557-1457-2-ND</b>
<b>MT29F4G16ABBDAH4:D</b>	<b>Contact Factory</b>	
<b>MT29F4G16ABBDAH4-IT:D</b>	<b>Contact Factory</b>	<b>557-1462-2-ND</b>
MT29F512G08CUCABH3-10ITZ:A	Contact Factory	
MT29F512G08CUCABH3-10Z:A	Contact Factory	
MT29F64G08AEEDBJ4-12:D	MT29F64G08AECABH1-10ITZ:A	
MT29F64G08CBAAAWP-ITZ:A	MT29F64G08CBABBWP-12IT:B	
MT29F64G08CBABAWP-IT:B	MT29F64G08CBABBWP-12IT:B	
MT29F64G08CBCDBJ4-6ITR:D		
MT29F8G16ADBDAH4-IT:D	Contact Factory	

Wafer

MT29F1G08ABAEAM68M3WC1	MT29F1G08ABAFAM78A3WC1	
MT29F1G08ABBDAM68A3WC1	MT29F1G08ABBFAM78A3WC1	
MT29F2G08ABAEAM69A3WC1	MT29F2G08ABAGAM79A3WC1	
MT29F2G08ABBEAM69A3WC1	MT29F2G08ABBGAM79A3WC1	
MT29F2G16ABBEAM69A3WC1	Contact Factory	
MT29F4G16ABBDAM60A3WC1	Contact Factory	

\*Materials that have been ordered are in **bold**.

---

<b>Method of Identification:</b>	Marketing Part Number
<b>Micron Sites Affected:</b>	Fab 6 - US
<b>Last Purchase Date*:</b>	2018-02-28
<b>Last Shipment Date:</b>	2018-08-28

---

\*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

**Micron Confidential and Proprietary Information**

Thank you

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.