

Light is OSRAM

16.04.2018

OS-IN-2018-014

Introduction of 2nd Source Supplier for TO56 Header

Subject of change:	Introduction of 2 nd Source Supplier for TO56 Header	
Affected products:	Please refer to attached product list <i>Product_List_OS-IN-2018-014.pdf</i>	
Reason for change:	<ul style="list-style-type: none"> • Improvement on Fine Leak Test yield loss • Capacity extension 	
Description of change	Introduction of new second source supplier 2 for TO56 header	
	<u>Current Status</u>	<u>New Status</u>
	Supplier 1	Supplier 1 and Supplier 2
Product identification:	Date code, Lot number	
Time schedule:	<ul style="list-style-type: none"> • Reliability data 	
	interim report 500h	30 th April 2018
	final report 1000h	20 th May 2018
	<ul style="list-style-type: none"> • Samples available 	6 th May 2018
	<ul style="list-style-type: none"> • Production release 	6 th May 2018
	<ul style="list-style-type: none"> • Start of delivery of new design 	1 st July 2018 onwards
Assessment:	<ul style="list-style-type: none"> • No change in the physical dimensions of the TO56 header • No change of the electrical and optical parameter • The data sheet remains unchanged 	

Please direct your inquiry to your local Sales office.

OSRAM Opto Semiconductors
GmbH

Head Office:

Leibnizstrasse 4
93055 Regensburg, Germany
Phone +49 941 850-5
Fax +49 941 850-1002
www.osram-os.com

Products Affected by Information Notification

Number: OS-IN-2018-014

Name: Introduction of 2nd Source Supplier for TO56 Header

Release Date: 4/16/2018

Implementation Date: 7/1/2018

<i>Product</i>	<i>QNumber</i>	<i>QNumber Description</i>	<i>Part Number</i>
PLT5 450B	Q65111A7459	PLT5 450B	PLT5 450B
PLT5 510	Q65111A6310	PLT5 510	PLT5 510