



End of Life Notification

Date: April 22, 2016

Subject: TDK discontinues non-profitable and low demand multilayer and dipped radial ceramic capacitor products

To whom it may concern,

Thank you for your business and continued interest in TDK's ceramic capacitors. This letter is to inform you that we are discontinuing the attached list of non-profitable and or low demand ceramic capacitor products.

This discontinuation will be finalized on **March 31, 2017**. All last time buy orders will be accepted until **December 31, 2016**. TDK is committed to work closely with you to minimize any impact this may have on your products. Please observe the discontinuation table attached to obtain the affected part numbers with reference to last time buy, last shipment, and end of life dates. Please reply to your local TDK representative by **10/31/2016**.

List of Affected Product:

Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
1	C0402JB0G103K020BC	C0402JB0G103KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
2	C0402JB0G103M020BC	C0402JB0G103MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
3	C0402JB0G332K020BC	C0402JB0G332KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
4	C0402JB0G332M020BC	C0402JB0G332MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
5	C0402JB0G472K020BC	C0402JB0G472KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
6	C0402JB0G472M020BC	C0402JB0G472MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
7	C0402JB0G682K020BC	C0402JB0G682KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
8	C0402JB0G682M020BC	C0402JB0G682MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-



End of Life Notification

Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
9	C0402JB0J103K020BC	C0402JB0J103KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
10	C0402JB0J103M020BC	C0402JB0J103MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
11	C0402JB0J332K020BC	C0402JB0J332KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
12	C0402JB0J332M020BC	C0402JB0J332MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
13	C0402JB0J472K020BC	C0402JB0J472KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
14	C0402JB0J472M020BC	C0402JB0J472MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
15	C0402JB0J682K020BC	C0402JB0J682KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
16	C0402JB0J682M020BC	C0402JB0J682MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
17	C0402JB1A103K020BC	C0402JB1A103KT00NN	2013/July	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
18	C0402JB1A103M020BC	C0402JB1A103MT00NN	2013/July	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
19	C0402JB1A332K020BC	C0402JB1A332KT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
20	C0402JB1A332M020BC	C0402JB1A332MT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
21	C0402JB1A472K020BC	C0402JB1A472KT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
22	C0402JB1A472M020BC	C0402JB1A472MT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
23	C0402JB1A682K020BC	C0402JB1A682KT00NN	2013/July	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
24	C0402JB1A682M020BC	C0402JB1A682MT00NN	2013/July	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
25	C0402X5R0G103K020BC	C0402X5R0G103KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
26	C0402X5R0G103M020BC	C0402X5R0G103MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
27	C0402X5R0G332K020BC	C0402X5R0G332KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
28	C0402X5R0G332M020BC	C0402X5R0G332MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
29	C0402X5R0G472K020BC	C0402X5R0G472KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
30	C0402X5R0G472M020BC	C0402X5R0G472MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
31	C0402X5R0G682K020BC	C0402X5R0G682KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
32	C0402X5R0G682M020BC	C0402X5R0G682MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-



End of Life Notification

Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
33	C0402X5R0J103K020BC	C0402X5R0J103KT00NN	2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
34	C0402X5R0J103M020BC	C0402X5R0J103MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
35	C0402X5R0J332K020BC	C0402X5R0J332KT00NN	2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
36	C0402X5R0J332M020BC	C0402X5R0J332MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
37	C0402X5R0J472K020BC	C0402X5R0J472KT00NN	2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
38	C0402X5R0J472M020BC	C0402X5R0J472MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
39	C0402X5R0J682K020BC	C0402X5R0J682KT00NN	2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
40	C0402X5R0J682M020BC	C0402X5R0J682MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
41	C0402X5R1A103K020BC	C0402X5R1A103KT00NN	2013/July	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
42	C0402X5R1A103M020BC	C0402X5R1A103MT00NN	2013/July	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
43	C0402X5R1A332K020BC	C0402X5R1A332KT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
44	C0402X5R1A332M020BC	C0402X5R1A332MT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
45	C0402X5R1A472K020BC	C0402X5R1A472KT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
46	C0402X5R1A472M020BC	C0402X5R1A472MT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
47	C0402X5R1A682K020BC	C0402X5R1A682KT00NN	2013/July	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
48	C0402X5R1A682M020BC	C0402X5R1A682MT00NN	2013/July	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
49	C0603JB0J104K030BC	C0603JB0J104KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603JB1A104K030BC	Alternative Suggestion is the 10V item
50	C0603JB0J104M030BC	C0603JB0J104MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603JB1A104M030BC	Alternative Suggestion is the 10V item
51	C0603JB0J223K030BC	C0603JB0J223KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603JB1E223K030BB	Alternative Suggestion is the 25V item
52	C0603JB0J223M030BC	C0603JB0J223MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603JB1E223M030BB	Alternative Suggestion is the 25V item
53	C0603JB0J333K030BC	C0603JB0J333KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
54	C0603JB0J333M030BC	C0603JB0J333MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
55	C0603JB0J473K030BC	C0603JB0J473KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603JB1E473K030BB	Alternative Suggestion is the 25V item
56	C0603JB0J473M030BC	C0603JB0J473MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603JB1E473M030BB	Alternative Suggestion is the 25V item
57	C0603JB0J683K030BC	C0603JB0J683KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-

End of Life Notification



Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
58	C0603JB0J683M030BC	C0603JB0J683MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
59	C0603JB1A223K030BC	C0603JB1A223KT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603JB1E223K030BB	Alternative Suggestion is the 25V item
60	C0603JB1A223M030BC	C0603JB1A223MT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603JB1E223M030BB	Alternative Suggestion is the 25V item
61	C0603JB1A333K030BC	C0603JB1A333KT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
62	C0603JB1A333M030BC	C0603JB1A333MT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
63	C0603JB1A473K030BC	C0603JB1A473KT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603JB1E473K030BB	Alternative Suggestion is the 25V item
64	C0603JB1A473M030BC	C0603JB1A473MT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603JB1E473M030BB	Alternative Suggestion is the 25V item
65	C0603JB1A683K030BC	C0603JB1A683KT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
66	C0603JB1A683M030BC	C0603JB1A683MT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
67	C0603X5R0J104K030BC	C0603X5R0J104KT00NN	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C0603X5R1A104K030BC	Alternative Suggestion is the 10V item
68	C0603X5R0J104M030BC	C0603X5R0J104MT00NN	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C0603X5R1A104M030BC	Alternative Suggestion is the 10V item
69	C0603X5R0J223K030BC	C0603X5R0J223KT00NN	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C0603X5R1E223K030BB	Alternative Suggestion is the 25V item
70	C0603X5R0J223M030BC	C0603X5R0J223MT00NN	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C0603X5R1E223M030BB	Alternative Suggestion is the 25V item
71	C0603X5R0J333K030BC	C0603X5R0J333KT00NN	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
72	C0603X5R0J333M030BC	C0603X5R0J333MT00NN	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
73	C0603X5R0J473K030BC	C0603X5R0J473KT00NN	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C0603X5R1E473K030BB	Alternative Suggestion is the 25V item
74	C0603X5R0J473M030BC	C0603X5R0J473MT00NN	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C0603X5R1E473M030BB	Alternative Suggestion is the 25V item
75	C0603X5R0J683K030BC	C0603X5R0J683KT00NN	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
76	C0603X5R0J683M030BC	C0603X5R0J683MT00NN	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
77	C0603X5R1A223K030BC	C0603X5R1A223KT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603X5R1E223K030BB	Alternative Suggestion is the 25V item
78	C0603X5R1A223M030BC	C0603X5R1A223MT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603X5R1E223M030BB	Alternative Suggestion is the 25V item
79	C0603X5R1A333K030BC	C0603X5R1A333KT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-

End of Life Notification



Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
80	C0603X5R1A333M030BC	C0603X5R1A333MT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
81	C0603X5R1A473K030BC	C0603X5R1A473KT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603X5R1E473K030BB	Alternative Suggestion is the 25V item
82	C0603X5R1A473M030BC	C0603X5R1A473MT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603X5R1E473M030BB	Alternative Suggestion is the 25V item
83	C0603X5R1A683K030BC	C0603X5R1A683KT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
84	C0603X5R1A683M030BC	C0603X5R1A683MT00NE	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
85	C0603X6S0G104K030BC	C0603X6S0G104KT00NN	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C0603X6S0J104K030BC	Alternative Suggestion is the 6.3V item
86	C0603X6S0G104M030BC	C0603X6S0G104MT00NN	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C0603X6S0J104M030BC	Alternative Suggestion is the 6.3V item
87	C0603X6S0G223K030BC	C0603X6S0G223KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603X6S1A223K030BB	Alternative Suggestion is the 10V item
88	C0603X6S0G223M030BC	C0603X6S0G223MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603X6S1A223M030BB	Alternative Suggestion is the 10V item
89	C0603X6S0G473K030BC	C0603X6S0G473KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603X6S1A473K030BB	Alternative Suggestion is the 10V item
90	C0603X6S0G473M030BC	C0603X6S0G473MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C0603X6S1A473M030BB	Alternative Suggestion is the 10V item
91	C0603X6S0G683K030BC	C0603X6S0G683KT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
92	C0603X6S0G683M030BC	C0603X6S0G683MT00NN	2013/Mar	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
93	C1005JB0J105K050BB	C1005JB0J105KT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1A105K050BB	Alternative Suggestion is the 10V item
94	C1005JB0J105M050BB	C1005JB0J105MT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1A105M050BB	Alternative Suggestion is the 10V item
95	C1005JB0J154K050BB	C1005JB0J154KT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C154K050BB	Alternative Suggestion is the 16V item
96	C1005JB0J154M050BB	C1005JB0J154MT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C154M050BB	Alternative Suggestion is the 16V item
97	C1005JB0J224K050BB	C1005JB0J224KT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C224K050BB	Alternative Suggestion is the 16V item
98	C1005JB0J224M050BB	C1005JB0J224MT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C224M050BB	Alternative Suggestion is the 16V item
99	C1005JB0J334K050BB	C1005JB0J334KT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C334K050BC	Alternative Suggestion is the 16V item
100	C1005JB0J334M050BB	C1005JB0J334MT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C334M050BC	Alternative Suggestion is the 16V item
101	C1005JB0J474K050BB	C1005JB0J474KT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C474K050BC	Alternative Suggestion is the 16V item
102	C1005JB0J474M050BB	C1005JB0J474MT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C474M050BC	Alternative Suggestion is the 16V item

End of Life Notification



Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
103	C1005JB0J684K050BB	C1005JB0J684KT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C684K050BC	Alternative Suggestion is the 16V item
104	C1005JB0J684M050BB	C1005JB0J684MT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C684M050BC	Alternative Suggestion is the 16V item
105	C1005JB1A105K050BB	C1005JB1A105KT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C105K050BC	Alternative Suggestion is the 16V item
106	C1005JB1A105M050BB	C1005JB1A105MT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C105M050BC	Alternative Suggestion is the 16V item
107	C1005JB1A154K050BC	C1005JB1A154KT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C154K050BB	Alternative Suggestion is the 16V item
108	C1005JB1A154M050BC	C1005JB1A154MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C154M050BB	Alternative Suggestion is the 16V item
109	C1005JB1A224K050BC	C1005JB1A224KT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C224K050BB	Alternative Suggestion is the 16V item
110	C1005JB1A224M050BC	C1005JB1A224MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C224M050BB	Alternative Suggestion is the 16V item
111	C1005JB1A334K050BC	C1005JB1A334KT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C334K050BC	Alternative Suggestion is the 16V item
112	C1005JB1A334M050BC	C1005JB1A334MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C334M050BC	Alternative Suggestion is the 16V item
113	C1005JB1A474K050BC	C1005JB1A474KT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C474K050BC	Alternative Suggestion is the 16V item
114	C1005JB1A474M050BC	C1005JB1A474MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C474M050BC	Alternative Suggestion is the 16V item
115	C1005JB1A684K050BC	C1005JB1A684KT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C684K050BC	Alternative Suggestion is the 16V item
116	C1005JB1A684M050BC	C1005JB1A684MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005JB1C684M050BC	Alternative Suggestion is the 16V item
117	C1005X5R0J105K050BB	C1005X5R0J105KT000F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1C105K050BC	Alternative Suggestion is the 16V item
118	C1005X5R0J105M050BB	C1005X5R0J105MT000F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1C105M050BC	Alternative Suggestion is the 16V item
119	C1005X5R0J154K050BB	C1005X5R0J154KT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005X5R1C154K050BB	Alternative Suggestion is the 16V item
120	C1005X5R0J154M050BB	C1005X5R0J154MT000F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005X5R1C154M050BB	Alternative Suggestion is the 16V item
121	C1005X5R0J224K050BB	C1005X5R0J224KTK00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1C224K050BB	Alternative Suggestion is the 16V item
122	C1005X5R0J224M050BB	C1005X5R0J224MTK00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1C224M050BB	Alternative Suggestion is the 16V item
123	C1005X5R0J334K050BB	C1005X5R0J334KTK00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1E334K050BB	Alternative Suggestion is the 25V item
124	C1005X5R0J334M050BB	C1005X5R0J334MTK00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1E334M050BB	Alternative Suggestion is the 25V item



End of Life Notification

Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
125	C1005X5R0J474K050BB	C1005X5R0J474KTK00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1E474K050BB	Alternative Suggestion is the 25V item
126	C1005X5R0J474M050BB	C1005X5R0J474MTK00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1E474M050BB	Alternative Suggestion is the 25V item
127	C1005X5R1A105K050BB	C1005X5R1A105KT00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1C105K050BC	Alternative Suggestion is the 16V item
128	C1005X5R1A105M050BB	C1005X5R1A105MT00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1C105M050BC	Alternative Suggestion is the 16V item
129	C1005X5R1A154K050BC	C1005X5R1A154KT00E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005X5R1C154K050BB	Alternative Suggestion is the 16V item
130	C1005X5R1A154M050BC	C1005X5R1A154MT00E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005X5R1C154M050BB	Alternative Suggestion is the 16V item
131	C1005X5R1A224K050BC	C1005X5R1A224KTK00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1C224K050BB	Alternative Suggestion is the 16V item
132	C1005X5R1A224M050BC	C1005X5R1A224MTK00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1C224M050BB	Alternative Suggestion is the 16V item
133	C1005X5R1A334K050BB	C1005X5R1A334KTK00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1E334K050BB	Alternative Suggestion is the 25V item
134	C1005X5R1A334M050BB	C1005X5R1A334MTK00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1E334M050BB	Alternative Suggestion is the 25V item
135	C1005X5R1A474K050BB	C1005X5R1A474KTK00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1E474K050BB	Alternative Suggestion is the 25V item
136	C1005X5R1A474M050BB	C1005X5R1A474MTK00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1E474M050BB	Alternative Suggestion is the 25V item
137	C1005X5R1C334K050BC	C1005X5R1C334KTK00E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1E334K050BB	Alternative Suggestion is the 25V item
138	C1005X5R1C334M050BC	C1005X5R1C334MTK00E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1E334M050BB	Alternative Suggestion is the 25V item
139	C1005X5R1C474K050BC	C1005X5R1C474KTK00E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1E474K050BB	Alternative Suggestion is the 25V item
140	C1005X5R1C474M050BC	C1005X5R1C474MTK00E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X5R1E474M050BB	Alternative Suggestion is the 25V item
141	C1005X6S0G105K050BB	C1005X6S0G105KT00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X6S1A105K050BC	Alternative Suggestion is the 10V item
142	C1005X6S0G105M050BB	C1005X6S0G105MT00F	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X6S1A105M050BC	Alternative Suggestion is the 10V item
143	C1005X6S0G154K050BB	C1005X6S0G154KT00F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005X6S1C154K050BB	Alternative Suggestion is the 16V item
144	C1005X6S0G154M050BB	C1005X6S0G154MT00F	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005X6S1C154M050BB	Alternative Suggestion is the 16V item



End of Life Notification

Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
145	C1005X6S0G224K050BB	C1005X6S0G224KT000F	2014/July	3/31/2017	12/31/2016	3/31/2017	C1005X6S1C224K050BB	Alternative Suggestion is the 16V item
146	C1005X6S0G224M050BB	C1005X6S0G224MT000F	2014/July	3/31/2017	12/31/2016	3/31/2017	C1005X6S1C224M050BB	Alternative Suggestion is the 16V item
147	C1005X6S0J105K050BC	C1005X6S0J105KT000E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X6S1A105K050BC	Alternative Suggestion is the 10V item
148	C1005X6S0J105M050BC	C1005X6S0J105MT000E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X6S1A105M050BC	Alternative Suggestion is the 10V item
149	C1005X6S0J154K050BC	C1005X6S0J154KT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005X6S1C154K050BB	Alternative Suggestion is the 16V item
150	C1005X6S0J154M050BC	C1005X6S0J154MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005X6S1C154M050BB	Alternative Suggestion is the 16V item
151	C1005X6S0J224K050BC	C1005X6S0J224KT000E	2014/July	3/31/2017	12/31/2016	3/31/2017	C1005X6S1C224K050BB	Alternative Suggestion is the 16V item
152	C1005X6S0J224M050BC	C1005X6S0J224MT000E	2014/July	3/31/2017	12/31/2016	3/31/2017	C1005X6S1C224M050BB	Alternative Suggestion is the 16V item
153	C1005X6S0J474K050BC	C1005X6S0J474KT000E	2011/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X6S1A474K050BC	Alternative Suggestion is the 10V item
154	C1005X6S0J474M050BC	C1005X6S0J474MT000E	2011/Apr	3/31/2017	12/31/2016	3/31/2017	C1005X6S1A474M050BC	Alternative Suggestion is the 10V item
155	C1005X6S0J684K050BC	C1005X6S0J684KT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005X6S1A684K050BC	Alternative Suggestion is the 10V item
156	C1005X6S0J684M050BC	C1005X6S0J684MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1005X6S1A684M050BC	Alternative Suggestion is the 10V item
157	C1608JB0J155K080AB	C1608JB0J155KT000N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608JB1C155K080AB	Alternative Suggestion is the 16V item
158	C1608JB0J155M080AB	C1608JB0J155MT000N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608JB1C155M080AB	Alternative Suggestion is the 16V item
159	C1608JB0J225K080AB	C1608JB0J225KT000N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608JB1C225K080AB	Alternative Suggestion is the 16V item
160	C1608JB0J225M080AB	C1608JB0J225MT000N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608JB1C225M080AB	Alternative Suggestion is the 16V item
161	C1608JB0J335K080AB	C1608JB0J335KT000N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608JB1A335K080AB	Alternative Suggestion is the 10V item
162	C1608JB0J335M080AB	C1608JB0J335MT000N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608JB1A335M080AB	Alternative Suggestion is the 10V item
163	C1608JB0J475K080AB	C1608JB0J475KT000N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608JB1A475K080AB	Alternative Suggestion is the 10V item
164	C1608JB0J475M080AB	C1608JB0J475MT000N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608JB1A475M080AB	Alternative Suggestion is the 10V item
165	C1608JB1A155K080AC	C1608JB1A155KT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608JB1C155K080AB	Alternative Suggestion is the 16V item
166	C1608JB1A155M080AC	C1608JB1A155MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608JB1C155M080AB	Alternative Suggestion is the 16V item
167	C1608JB1A225K080AC	C1608JB1A225KT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608JB1C225K080AB	Alternative Suggestion is the 16V item
168	C1608JB1A225M080AC	C1608JB1A225MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608JB1C225M080AB	Alternative Suggestion is the 16V item
169	C1608X5R0J155K080AB	C1608X5R0J155KT000N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C155K080AB	Alternative Suggestion is the 16V item



End of Life Notification

Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
170	C1608X5R0J155M080AB	C1608X5R0J155MTK00N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C155M080AB	Alternative Suggestion is the 16V item
171	C1608X5R0J225K080AB	C1608X5R0J225KT00N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C225K080AB	Alternative Suggestion is the 16V item
172	C1608X5R0J225M080AB	C1608X5R0J225MT00N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C225M080AB	Alternative Suggestion is the 16V item
173	C1608X5R0J335K080AB	C1608X5R0J335KT00N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C335K080AC	Alternative Suggestion is the 16V item
174	C1608X5R0J335M080AB	C1608X5R0J335MTK00N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C335M080AC	Alternative Suggestion is the 16V item
175	C1608X5R0J475K080AB	C1608X5R0J475KTJ00N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C475K080AC	Alternative Suggestion is the 16V item
176	C1608X5R0J475M080AB	C1608X5R0J475MTJ00N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C475M080AC	Alternative Suggestion is the 16V item
177	C1608X5R1A155K080AB	C1608X5R1A155KT00N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C155K080AB	Alternative Suggestion is the 16V item
178	C1608X5R1A155M080AB	C1608X5R1A155MTK00N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C155M080AB	Alternative Suggestion is the 16V item
179	C1608X5R1A225K080AC	C1608X5R1A225KT00E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C225K080AB	Alternative Suggestion is the 16V item
180	C1608X5R1A225M080AC	C1608X5R1A225MT00E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C225M080AB	Alternative Suggestion is the 16V item
181	C1608X5R1A335K080AC	C1608X5R1A335KT00E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C335K080AC	Alternative Suggestion is the 16V item
182	C1608X5R1A335M080AC	C1608X5R1A335MTK00E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C335M080AC	Alternative Suggestion is the 16V item
183	C1608X5R1A475K080AC	C1608X5R1A475KTJ00E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C475K080AC	Alternative Suggestion is the 16V item
184	C1608X5R1A475M080AC	C1608X5R1A475MTJ00E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C1608X5R1C475M080AC	Alternative Suggestion is the 16V item
185	C2012JB0J106K085AB	C2012JB0J106KT0J5N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012JB1C106K085AC	Alternative Suggestion is the 16V item
186	C2012JB0J106K125AB	C2012JB0J106KT00N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X6S0J106K125AB	Alternative Suggestion is the X6S item
187	C2012JB0J106M085AB	C2012JB0J106MT0J5N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012JB1C106M085AC	Alternative Suggestion is the 16V item
188	C2012JB0J106M125AB	C2012JB0J106MT00N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X6S0J106M125AB	Alternative Suggestion is the X6S item
189	C2012JB0J475K085AB	C2012JB0J475KT0J0N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012JB1A475K060AB	Alternative Suggestion is the 10V/0.60mm item
190	C2012JB0J475M085AB	C2012JB0J475MT0J0N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012JB1A475M060AB	Alternative Suggestion is the 10V/0.60mm item
191	C2012JB0J685K085AB	C2012JB0J685KT0J0N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012JB1A685K060AC	Alternative Suggestion is the 10V/0.60mm item
192	C2012JB0J685K125AB	C2012JB0J685KT00N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X7R0J685K125AB	Alternative Suggestion is the X7R item



End of Life Notification

Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
193	C2012JB0J685M085AB	C2012JB0J685MT0J0N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012JB1A685M060AC	Alternative Suggestion is the 10V/0.60mm item
194	C2012JB0J685M125AB	C2012JB0J685MT000N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X7R0J685M125AB	Alternative Suggestion is the X7R item
195	C2012JB1A106K085AC	C2012JB1A106KT0J5E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012JB1C106K085AC	Alternative Suggestion is the 16V item
196	C2012JB1A106K125AC	C2012JB1A106KT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X6S1A106K125AB	Alternative Suggestion is the X6S item
197	C2012JB1A106M085AC	C2012JB1A106MT0J5E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012JB1C106M085AC	Alternative Suggestion is the 16V item
198	C2012JB1A106M125AC	C2012JB1A106MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X6S1A106M125AB	Alternative Suggestion is the X6S item
199	C2012JB1A685K085AC	C2012JB1A685KT0J0E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X5R1A685K085AB	Alternative Suggestion is the X5R item
200	C2012JB1A685K125AC	C2012JB1A685KT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X6S1A685K125AB	Alternative Suggestion is the X6S item
201	C2012JB1A685M085AC	C2012JB1A685MT0J0E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X5R1A685M085AB	Alternative Suggestion is the X5R item
202	C2012JB1A685M125AC	C2012JB1A685MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X6S1A685M125AB	Alternative Suggestion is the X6S item
203	C2012X5R0J106K125AB	C2012X5R0J106KT000N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X6S0J106K125AB	Alternative Suggestion is the X6S item
204	C2012X5R0J106M125AB	C2012X5R0J106MT000N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X6S0J106M125AB	Alternative Suggestion is the X6S item
205	C2012X5R0J475K085AB	C2012X5R0J475KTKJ0N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X7R0J475K085AB	Alternative Suggestion is the X7R item
206	C2012X5R0J475K125AA	C2012X5R0J475KT0S0N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X5R1A475K125AA	Alternative Suggestion is the 10V item
207	C2012X5R0J475M085AB	C2012X5R0J475MTKJ0N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X7R0J475M085AB	Alternative Suggestion is the X7R item
208	C2012X5R0J475M125AA	C2012X5R0J475MT0S0N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X5R1A475M125AA	Alternative Suggestion is the 10V item
209	C2012X5R0J685K125AB	C2012X5R0J685KTK00N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X7R0J685K125AB	Alternative Suggestion is the X7R item
210	C2012X5R0J685M125AB	C2012X5R0J685MTK00N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X7R0J685M125AB	Alternative Suggestion is the X7R item
211	C2012X5R1A106K125AB	C2012X5R1A106KT000E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X6S1A106K125AB	Alternative Suggestion is the X6S item
212	C2012X5R1A106M125AB	C2012X5R1A106MT000E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X6S1A106M125AB	Alternative Suggestion is the X6S item
213	C2012X5R1A475K085AC	C2012X5R1A475KT0J0E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X6S1A475K085AB	Alternative Suggestion is the X6S item
214	C2012X5R1A475M085AC	C2012X5R1A475MT0J0E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X6S1A475M085AB	Alternative Suggestion is the X6S item
215	C2012X5R1A685K125AB	C2012X5R1A685KTK00N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X6S1A685K125AB	Alternative Suggestion is the X6S item
216	C2012X5R1A685M125AB	C2012X5R1A685MTK00N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X6S1A685M125AB	Alternative Suggestion is the X6S item
217	C2012X5R1C106K125AC	C2012X5R1C106KTJ00E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X6S1C106K125AC	Alternative Suggestion is the X6S item



End of Life Notification

Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
218	C2012X5R1C106M125AC	C2012X5R1C106MTJ00E	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X6S1C106M125AC	Alternative Suggestion is the X6S item
219	C2012X5R1C685K125AC	C2012X5R1C685KTK00E	2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X6S1C685K125AC	Alternative Suggestion is the X6S item
220	C2012X5R1C685M125AC	C2012X5R1C685MTK00E	2010/Apr	3/31/2017	12/31/2016	3/31/2017	C2012X6S1C685M125AC	Alternative Suggestion is the X6S item
221	C2012X6S0G106K125AC	C2012X6S0G106KT000N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X6S0J106K125AB	Alternative Suggestion is the 6.3V item
222	C2012X6S0G106M125AC	C2012X6S0G106MT000N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C2012X6S0J106M125AB	Alternative Suggestion is the 6.3V item
223	C3216JB1A156M160AC	C3216JB1A156MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C3216JB1C156M160AB	Alternative Suggestion is the 16V item
224	C3216JB1A226M160AC	C3216JB1A226MT000E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C3216JB1C226M160AB	Alternative Suggestion is the 16V item
225	C3216X5R0J226M160AA	C3216X5R0J226MT000N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C3216X6S0J226M160AB	Alternative Suggestion is the X6S item
226	C3216X5R1A106K160AB	C3216X5R1A106KTK00N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C3216X5R1C106K160AA	Alternative Suggestion is the 16V item
227	C3216X5R1A106M160AB	C3216X5R1A106MTK00N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	C3216X5R1C106M160AA	Alternative Suggestion is the 16V item
228	C3216X5R1A156M160AB	C3216X5R1A156MTK00N	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C3216X5R1C156M160AB	Alternative Suggestion is the 16V item
229	C3216X5R1A226M160AC	C3216X5R1A226MT000E	2010/Oct	3/31/2017	12/31/2016	3/31/2017	C3216X6S1A226M160AB	Alternative Suggestion is the X6S item
230	C3216X5R1C106K085AC	C3216X5R1C106KTKJ0E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C3216X6S1C106K085AC	Alternative Suggestion is the X6S item
231	C3216X5R1C106M085AC	C3216X5R1C106MTKJ0E	2013/Mar	3/31/2017	12/31/2016	3/31/2017	C3216X6S1C106M085AC	Alternative Suggestion is the X6S item
232	YFF21PC0J106M	YFF21PC0J106MT000N	2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
233	YFF21PC1A225M	YFF21PC1A225MT000N	2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
234	YFF21PC1A475M	YFF21PC1A475MT000N	2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
235	YFF31PC0J226M	YFF31PC0J226MT000N	2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
236	YNA21B1C0G106M	YNA21B1J0G106MT000N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
237	YNA21B1J0G106M	YNA21B1J0G106MT000N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
238	YNA21B2A0G106M	YNA21B2A0G106MT000N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
239	YNA21B2C0G106M	YNA21B2C0G106MT000N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-
240	YNA21B2J0G106M	YNA21B2J0G106MT000N	Before 2010/Apr	3/31/2017	12/31/2016	3/31/2017	No Alternative	-



End of Life Notification

Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
241	FK14X5R0J106K	FK14X5R0J106KR020	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK14X5R1A106KR020	Alternative suggestion is the 10V item
242	FK14X5R0J106KR006	FK14X5R0J106KR006	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK14X5R1A106KR026	Alternative suggestion is the 10V item
243	FK14X5R0J106M	FK14X5R0J106MR020	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK14X5R1A106MR020	Alternative suggestion is the 10V item
244	FK14X5R0J106MR006	FK14X5R0J106MR006	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK14X5R1A106MR026	Alternative suggestion is the 10V item
245	FK14X5R0J685K	FK14X5R0J685KR020	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK14X5R1A685KR020	Alternative suggestion is the 10V item
246	FK14X5R0J685KR006	FK14X5R0J685KR006	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK14X5R1A685KR026	Alternative suggestion is the 10V item
247	FK16X5R0J226M	FK16X5R0J226MR020	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK11X5R0J226MN020	Alternative suggestion is the larger 6.3V item
248	FK16X5R0J226MR006	FK16X5R0J226MR006	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK11X5R0J226MN020	Alternative suggestion is the larger 6.3V item
249	FK16X5R1A106K	FK16X5R1A106KR020	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK16X5R1C106KN020	Alternative suggestion is the 16V item
250	FK16X5R1A106KR006	FK16X5R1A106KR006	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK16X5R1C106KN026	Alternative suggestion is the 16V item
251	FK16X5R1A106M	FK16X5R1A106MR020	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK16X5R1C106MN020	Alternative suggestion is the 16V item
252	FK16X5R1A106MR006	FK16X5R1A106MR006	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK16X5R1C106MN026	Alternative suggestion is the 16V item
253	FK18X5R0J155K	FK18X5R0J155KR020	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK18X5R1A155KR020	Alternative suggestion is the 10V item
254	FK18X5R0J155KR006	FK18X5R0J155KR006	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK18X5R1A155KR026	Alternative suggestion is the 10V item
255	FK18X5R0J225K	FK18X5R0J225KR020	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK18X5R1A225KR020	Alternative suggestion is the 10V item
256	FK18X5R0J225KR006	FK18X5R0J225KR006	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK18X5R1A225KR026	Alternative suggestion is the 10V item
257	FK18X5R0J335K	FK18X5R0J335KR020	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK18X5R1A335KR020	Alternative suggestion is the 10V item
258	FK18X5R0J335KR006	FK18X5R0J335KR006	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK18X5R1A335KR026	Alternative suggestion is the 10V item
259	FK18X5R0J475K	FK18X5R0J475KR020	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK18X5R1A475KR020	Alternative suggestion is the 10V item
260	FK18X5R0J475KR006	FK18X5R0J475KR006	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK18X5R1A475KR026	Alternative suggestion is the 10V item
261	FK24X5R0J106K	FK24X5R0J106KR000	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK24X5R1A106KR000	Alternative suggestion is the 10V item
262	FK24X5R0J106KR006	FK24X5R0J106KR006	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK24X5R1A106KR006	Alternative suggestion is the 10V item
263	FK24X5R0J106M	FK24X5R0J106MR000	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK24X5R1A106MR000	Alternative suggestion is the 10V item
264	FK24X5R0J106MR006	FK24X5R0J106MR006	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK24X5R1A106MR006	Alternative suggestion is the 10V item
265	FK24X5R0J685K	FK24X5R0J685KR000	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK24X5R1A685KR000	Alternative suggestion is the 10V item



End of Life Notification

Index	TDK Part Number	TDK Item Description	Released Date	EOL Date	LTB Date	Last Shipment Date	Alternative Suggestion	Alternative Comments
266	FK24X5R0J685KR006	FK24X5R0J685KR006	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK24X5R1A685KR006	Alternative suggestion is the 10V item
267	FK26X5R0J226M	FK26X5R0J226MR000	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK20X5R0J226MN000	Alternative suggestion is the larger 6.3V item
268	FK26X5R0J226MR006	FK26X5R0J226MR006	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK20X5R0J226MN000	Alternative suggestion is the larger 6.3V item
269	FK26X5R1A106K	FK26X5R1A106KP000	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK26X5R1C106KN000	Alternative suggestion is the 16V item
270	FK26X5R1A106KR006	FK26X5R1A106KR006	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK26X5R1C106KN006	Alternative suggestion is the 16V item
271	FK26X5R1A106M	FK26X5R1A106MP000	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK26X5R1C106MN000	Alternative suggestion is the 16V item
272	FK26X5R1A106MR006	FK26X5R1A106MR006	2011/Oct	3/31/2017	12/31/2016	3/31/2017	FK26X5R1C106MN006	Alternative suggestion is the 16V item
273	FK28X5R0J155K	FK28X5R0J155KR000	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK28X5R1A155KR000	Alternative suggestion is the 10V item
274	FK28X5R0J155KR006	FK28X5R0J155KR006	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK28X5R1A155KR006	Alternative suggestion is the 10V item
275	FK28X5R0J225K	FK28X5R0J225KR000	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK28X5R1A225KR000	Alternative suggestion is the 10V item
276	FK28X5R0J225KR006	FK28X5R0J225KR006	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK28X5R1A225KR006	Alternative suggestion is the 10V item
277	FK28X5R0J335K	FK28X5R0J335KR000	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK28X5R1A335KR000	Alternative suggestion is the 10V item
278	FK28X5R0J335KR006	FK28X5R0J335KR006	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK28X5R1A335KR006	Alternative suggestion is the 10V item
279	FK28X5R0J475K	FK28X5R0J475KR000	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK28X5R1A475KR000	Alternative suggestion is the 10V item
280	FK28X5R0J475KR006	FK28X5R0J475KR006	2012/Jan	3/31/2017	12/31/2016	3/31/2017	FK28X5R1A475KR006	Alternative suggestion is the 10V item

End of Life Notification



Authorized Signature for TDK Corporation

A handwritten signature in black ink that reads "S. Maloy". The signature is written in a cursive style with a horizontal line underneath it.

Name: Steve Maloy
Position: Director of Product Marketing
Department: Ceramic Capacitor Business Group
TDK Corporation of America
475 Half Day Road, Suite 300
Lincolnshire, IL 60069